



Photo 5. View on 6 - 6A wall F. Broken brick to outer edges shows this was internal wall. Original doorway.



Photo 131. Direction change to roof of harness room.



Photo 133. Detail of roof light.



Photo 134. Harness hooks still place.



Photo 135. Present outside door to north east was an internal door. Has double header arched head.