



Photo 192. Ventilated ridge to slated roof.



Large photo 136. Typical outside of stable block with good stock bricks.

Inset photo 193. Detail of brickwork with Queen closers to opening.




Photo 137. Detail of harness rack bolt.

Photo 142. Inside wall showing remains of harness rack.

