

Photo 158. Support bar hay rack.




Photo 150. Rack fixing bolt.

Photo 147. Divided stable at north east with feed trough and hay racks in place.



Photo 154. Harness rack fitted under tiebeam. Were fitted to both sides of the opening



Photo 149. Brick floor with slope and run off still survives to most of floor area.