



A general view looking north through the nave of the barn, A, showing the rear aisle main trusses to tiebeam level and salvaged timbers from the collapsed roof. Stabilising timbers are bolted through the structure and into the midstreys.

A view into the north midstrey showing the nineteenth century door structure with leap boards below for which partial slots survive on the main door posts. It has a side purlin roof with one framed collar and one bird's mouth jointed to the purlin. At the lower front left, north, is a side access door.