

Barn, A. View of two northern bays on the east wall. Shows the typical primary braced frame structure found through the barn. Note reused toplate as midrail.



16.CNV

Barn, A. View to west aisle showing extended width rear nineteenth century doors opposite each of the midstreys. Aisle wall to right original, to left rebuilt in nineteenth century.