

Newhouse Farm, Purton End, Debden, Essex.



Granary south entrance side with brick formed steps to platform entrance. Pier walls return at each end and behind the steps from the intermediate walls. Weatherboarding part replaced as is plasterwork.



Granary entrance door appears original with lower patch repair



Granary west end to roadway with tarred brick plinth wall and weatherboarding and mixed age plaster above. The window is a later insertion.

Newhouse Farm, Purton End, Debden, Essex.



Granary east end with ashlar plaster to house. Late door insertion from modern garage. Note structural brace line in plaster and at bottom of door. Weatherboarding to left of door appears to be original.



Granary under view showing west support wall of mixed bond brickwork and softwood floor joists.



Granary under view showing north retaining wall against slope and intermediate pier wall. Note the amount of bark surviving on floor joists showing how maximum possible section was being produced from limited size trees.