

Newhouse Farm, Purton End, Debden, Essex.



Granary long inside view to west from under inserted floor of first bay. Visible tiebeam ends have iron brackets. Primary bracing to the walls. Ceiling plastered under collar level. Inserted window in west wall.



Granary view to north wall showing wall studs and wallplate. Above are rafters set evenly along the roof with no principle trusses.

Newhouse Farm, Purton End, Debden, Essex.



Granary view to south west corner showing wallplate and tiebeam joint with iron bracket. Primary bracing to walls



Granary view to south entrance wall. Board door in central bay. Oak arch braces between tiebeam and post.