

Summers Hall East Barn, Blackmore End, Essex.



38

View in C19 west range looking up to show typical roof construction with reused timbers. Simple scarf joints but collars are pegged.



39

Detail in roof showing some reused timbers that have had their original cross section reduced possibly by sawing to increase the amount of available lengths. The window mullion mortises are in what is now a possibly quartered timber.



40

East wall of closed section of the west range, previously repaired with blockwork. Note vertical lines at cross divisions where end timber of infill was mortared to wall.



41

Window in the west wall of the range cut into the brickwork at a later date. This is beyond the area of conversion.



42

View of west C19 range from the south showing the end gable with doorway and an added window. Brick walling to east is all random coursed brick pieces.



43

Nag stable and trap building at southern end of yard and not part of present conversion. Possibly dates to about the middle of the nineteenth century.