

Photo No.1: Development site facing southeast



Photo No.2: Detail of hardcore deposit at north end of site