

High Crindledyke Farm, Carlisle, Cumbria **Standing Building Survey**

Report No. 1973







CFA ARCHAEOLOGY LTD

The Old Engine House Eskmills Business Park Musselburgh East Lothian EH21 7PQ

Tel: 0131 273 4380 Fax: 0131 273 4381

email: info@cfa-archaeology.co.uk web: www.cfa-archaeology.co.uk

Author	Michael Cressey BA MSc PhD MifA FSA Scot and
	Stuart Mitchell MA AIfA
Illustrator	Leeanne Whitelaw BSc MIfA
Editor	Bruce Glendinning BSc PgDip MIfA
Commissioned by	Story Homes Ltd
Date issued	December 2011
Version	0
Planning Application No	09/0617
Grid Ref	NY 3381 5604
Oasis Ref	cfaarcha1-113312

This document has been prepared in accordance with CFA Archaeology Ltd standard operating procedures.

High Crindledyke Farm, Carlisle, Cumbria Standing Building Survey

Report No. 1973

CONTENTS

2. 3. 4. 5. 6. 7.	Introduction Methodology Desk-based Assessment Results Building Survey Results Discussion Conclusions Recommendations Bibliography	4 5 6 7 15 16 16
Tables		
 2. 3. 4. 5. 	Building recording requirements at High Crindledyke Farm Tithe apportionment value of High Crindledyke Farm in 1820 Census Returns by year listing the names of the tenant farmers at High Crindledyke Farm Function of the individual buildings on each range and relative phase Function, dimensions, observations in each room within the farmhouse Roof truss features in Building 4	5 6 7 11 11
APPE	NDICES	
1.	Digital Photograph Register	18
ILLUS	TRATIONS (bound at rear)	
Fig. 1 Fig 2a- Fig 3a Fig 3b Fig 3c Fig 3d Fig 4a Fig 4b Fig 5a Fig 5b Fig 6a Fig 6b		
PLATI	ES (bound at rear)	
Plate 1 Plate 2 Plate 3 Plate 4 Plate 5 Plate 6 Plate 7 Plate 8	East-facing entrance to Building 1 Interior of building 1 showing the steel roof trusses Part of the north-facing elevation of the South Range showing Buildings South-facing elevation of Buildings 2 and 3. North-facing elevation of the farmhouse South-facing elevation of the farmhouse West-facing gable of the farmhouse Room 1 fireplace	1-3

- Plate 9 Staircase and hall
- Plate 10 Staircase and landing
- Plate 11 Ornate hall floor possibly inspired by Arts and Crafts movement
- Plate 12 King-post roof truss (requires labels)
- Plate 13 The base of the king-post truss showing carpenters kit numbers
- Plate 14 West-facing elevation of Building 5
- Plate 15 South-facing gable of Building 5 showing blocked slit vents
- Plate 16 South-facing elevation of Building 8
- Plate 17 Interior of Building 8
- Plate 18 Timber mono roof in Building 9.

DIGITAL PHOTOGRAPHS (Copied to CD)

1. INTRODUCTION

1.1 General

This report presents the results of a Level 3 standing building survey undertaken by CFA Archaeology Ltd (CFA) at High Crindledyke Farm, Kingmoor, Carlisle, Cumbria (NGR NY 3381 5604, Fig. 1) during October 2011. The work was commissioned by Story Homes Ltd.

Item 17 of the Planning Statement produced by Cumbria County Council states that prior to the demolition of High Crindledyke Farm a Level 3 standing building survey will be undertaken in line with English Heritage (2006). A site visit was conducted by Dr Mike Cressey, CFA's Building Surveyor, in 2008 to assess the architectural character of High Crindledyke Farm, the results of which were incorporated into the cultural heritage statement of the Crindledyke Masterplan. A Written Scheme of Investigation (WSI) was produced by CFA and based upon documents passed to CFA by Story Homes. The WSI was agreed by Jeremy Parsons, Cumbria County Council's Archaeologist preceding the building survey.

1.2 Background

Crindledyke Farm is a typical courtyard steading with three ranges surrounding the farmyard (Fig. 1). The farmhouse dates to the late 18th century and is built of red brick, with three sides covered in a wet-dash render. The north-facing elevation, which is render free, has three bays, the middle of which has an off-set doorway surmounted by an arched window lighting the main staircase. Projecting off the east gable are a series of ancillary buildings of mixed date ranging from the early 19th century to 20th century. The south elevation is rendered and has three bays which incorporate a central doorway and square-headed windows with white painted raised-margins.

The north range has been partly demolished following a recent fire, although the surviving elements appear to date to the late 18th century and includes the shell of a lofted barn with slit vents. A section of wall that is related to another rectangular building forms the load bearing wall for two modern sheds. The west range incorporates a brick-built threshing barn which has been converted into a grain silo. This is attached to a modern steel-framed workshop and lean-to implement shed.

2. Objectives

The objectives of the programmes of archaeological works were:

- 1. To carry out a desk-based assessment and place the farm in its historical context and to provide details, where known, on the building's architects, builders, patrons and owners.
- 2. To produce a Level 3 standing building record of the farmhouse, barns and all associated agricultural buildings
- 3. To produce a Historic Building Survey report outlining the results of the work.

2. METHODOLOGY

2.1 General

CFA follows the Institute for Archaeologists' Code of Conduct, Standards and Guidelines for Historic Building Survey as appropriate.

2.2 Desk-based Assessment

An examination of readily available desk-based sources, namely historical maps and information on listed buildings and secondary sources relevant to local vernacular building traditions, were examined in the County Records Office, Carlisle. The maps examined are listed in Section 8. Extracts from the Census records for High Crindledyke Farm for the years 1841 to 1891 were also examined to provide the names of the residents and their occupation.

The desk-based survey was carried out prior to the commencement of the standing building survey. The Historic Environment Records Officer for Cumbria was contacted to determine what information was held on the SMR.

2.3 Building Survey

The specific building requirements approved by Cumbria County Council are listed in Table 1. Level 3 surveys are specified by English Heritage (English Heritage 2006) as an analytical record supported by historical and cartographic detail.

Building	Metric Survey	Photographic Survey
Farmhouse and ancillary	All exterior elevations to Level 3	All interior elevations to Level 3
buildings		
Farm House and ancillary	Ground & First floor plan to	All interior floors to Level 3
buildings	Level 3	
North and West Ranges	All exterior elevations to Level 3	All interior elevations to Level 3
North and West Ranges	Ground and first floor plans to	All interior floors to Level 3
	Level 3	

Table 1. Building recording requirements at High Crindledyke Farm

Building elevations were surveyed using an industry standard Total Station in REDM mode to create a series of wireframes which were transposed by Penmap and CAD to produce Figures 3a-c, 5a-b, and 6a-b. Ground and first floor plans (Figs 4a-b) of the farmhouse (Building 4) are based on measured sketches using a hand-held Leica distometer. The client's base map of the farmstead was annotated using the same method as above and included the addition of all building walls, partitions and openings.

A photographic record was maintained during the survey using a Nikon D300 camera. A catalogue of digital images produced is included in Appendix 1 and copied to CD.

All interiors were photographed on a room by room basis. Each room was afforded a unique unit number to allow cross-reference to the photographic record. The photographs were taken on the ordinal points to ensure comprehensive photographic cover. All internal building elevations were recorded by photography only.

3. DESK-BASED ASSESSMENT RESULTS

3.1 Cartographic

'High Grinel Dike' is shown at the current location of the farm on Thomas Donald's map of Cumberland dated 1774 (not shown). The 1820 tithe map (Fig 2a) depicts a courtyard farmstead named as *Cringle Dyke*. The farmhouse is depicted on the south range, with a rectilinear building situated on its east side. Two buildings are shown at the east end of the range aligned north-south. On the north range is a large rectangular building with a narrower building adjoining. At the east end there is a building built on to it at a right angle. On the west side there is a rectangular building with outshot entrance flanked by two smaller structures.

The 1865 First Edition Ordnance Survey map (Fig 2b) depicts a formal courtyard steading with the principal ranges surrounding the farmyard. The north range comprises a linear range with right-angle returns at each end and an outshot building on the north side. The farmhouse is depicted with a narrow rectilinear building on its east side. A single detached building is present to the east.

There are no notable changes on subsequent Ordnance Survey map editions. The 1901 Ordnance Survey map shows that the north range is unaltered while alterations have occurred at the east end of the south range with the addition of an L-shaped building. The 1939 revised Ordnance Survey map (Fig 2c) shows little further change, with extension northwards of the north range. There are some minor changes throughout its history in relation to ancillary buildings, probably lean-tos and sheds, around the core block but there is relatively little change in the basic layout of the steading since the mid 19th century. By 1974, the plan is the same as seen today.

3.2 Bibliographic

The Tithe Apportionment Schedule lists John Hewitt as the landowner with Christopher Blackburn as tenant (Table 2). The results show that arable farming was the main economic base of the farm during the early 19th century.

Landowner	Tenant	Item	Rent Charge
John Hewitt	Christopher Blackburn	Homestead	£0 2s.6d
Ditto	Ditto	Stack yard	£0.1s 9d
Ditto	Ditto	Orchard	£0 3s 6d.
Ditto	Ditto	Wood	£0 3s 0d
Ditto	Ditto	Arable	£48 13.3s

Table 2. Tithe apportionment value of Crindledyke Farm in 1820

The Cargo Parish census returns were examined and the names of the tenant farmers at High Crindledyke are shown in Table 3.

Year	Name	Mar. Status	Age
1841	George Irving	Married	40
1851	Thomas Baxter	Widower	77
1861	Thomas Blake	Married	44
1891	John Hodgson	Widower	82

Table 3. Census returns listing the names of the tenant farmers at Crindledyke Farm

4. BUILDING SURVEY RESULTS

4.1 General Description of the Buildings

The general layout of High Crindledyke farm is described here: this is confined to the main buildings (Buildings 1-5 and 7) only, as the rest are modern 20th century agricultural buildings of no historical interest. The buildings are described in clockwise order and are shown on the general layout plan. The functions of the buildings at the time of the survey are listed in Table 4. Numbers in bold and parentheses relate to architectural feature numbers on the respective elevation drawings.

Range	Building No	Function	Phase
South	1	Byre with adjoining chemical store	20 th century
South	2	Store shed and utility room	20 th century
South	3	Two storey domestic extension	19 th century core with 20 th century
			refurbishment
South	4	Farmhouse	Late 18 th century modernised in the
			20 th century
West	5	Barn/grain silo	Late 18 th century core with 20 th
			century alterations
West	6	Workshop	20 th century
North	7	Workshop/stores	Late 19 th century
North	8	Derelict barn	Late 18 th century
North	9	Lean-to shed	20 th century
North	10	Timber-framed barn	20 th century
North	11	Steel-framed implement shed	20 th century
North	12	Lean-to shed	20 th century

Table 4. Function of the individual buildings on each range and relative phase

4.2 South Range

4.2.1 Building 1: Byre

External detail

Building 1 comprises a brick-built byre that was originally a milking shed prior to its conversion to a byre. The building is rectangular and measures 13.4m by 5.6m. The north-facing elevation is largely featureless with red-brick walls (1/1) incorporating ventilation grilles (Fig 3a). The wall is built in English Garden bond (5:1). The roof is clad with corrugated asbestos (1/2). At the west end of the building there is a distinct break in build where the main build meets a section of earlier brickwork (1/3). A large sliding metal door (1/4) leads into a general storage area. The east gable (Fig. 3d, Plate 1) incorporates a large rectangular bay opening (1/5) but the sliding door has been removed. Above the doorway is a four-paned window (1/6).

Internal detail

Three composite iron A-frame trusses support the asbestos roof (Plate 2). The north and south-facing elevations have been rendered with cement to a height of 1.2m. Scars within the render mark the position of milking stalls. The floor is concrete with a central drain.

At the west end of the byre there are two compartments accessed by a doorway. One is a small chemical store measuring 4m by 1.2m and is unlit. The second is accessed by a small doorway in the partition wall. The storeroom measures 3.7m by 3.3m and access is gained to the courtyard through the large sliding door (1/4). The interior walls are whitewashed and featureless. The south-facing elevation is hidden behind a steel-framed shed.

4.2.2 Building 2: Stores and Utility Room

External detail

Building 2 occupies a rectangular footprint and is built of brick (2/1, English Garden bond 5:1) on the north-facing elevation (Fig. 3a, Plate 3) and a mixture of brick and cobbles on the south-facing elevation (Fig. 3c). The building is accessed by a double-leaved plank-built door (2/2) on the north-facing elevation. The pitched roof is coved with slate (2/3).

On the south elevation the facade is rendered (2/4) (Plate 4). A modern two-panelled door provides access (2/5). A two-paned window lights the utility room (2/6). A small square windowless opening (2/7) is present below eaves height.

Internal detail

The interior of Building 2 is partitioned by a brick wall forming two compartments. The easternmost room has a cobble-built whitewashed west-facing wall. The brick partition wall is featureless. The larger room is the farm's utility room measuring 6m by 5m. The room is accessed by a modern PVC door on the south-facing elevation and lit by a two-paned casement window. The ceiling is lined with tongue-and-grooved planks. A plank-built door provides access into a small storeroom and to the farmyard.

4.2.3 Building 3: Extension

External detail

Building 3 comprises a fairly recent refurbished extension. The exterior north-facing elevation incorporates a passage wall which is brick-built and covered with pebble-dash render (3/1) (Fig. 3a). A modern half-panelled door provides access to the interior of the extension and the main farmhouse (Building 4). A four-paned wooden window lights the passage (3/2). The passage lean-to roof is covered with slate (3/4). The main wall (3/5) of the extension is red-brick (English Garden bond 6:1). A two-paned window (3/6) is surmounted by a segmented flat arch. The pitched roof is covered with concrete roof tiles (3/7). The chimney stack (3/8) has been heightened by four courses of brick.

The exterior south-facing elevation is harled with pebble-dash render (3/9) (Fig. 3c). The fenestration includes a ground floor casement window (3/10) and a two-paned (1-over-1) casement on the first floor. The roof (3/7) is the same as on the south-facing elevation.

Interior ground floor

A single room is present on the ground floor (Room 8) which measures 5.1m by 4.5m (Fig 4a). The room is lit by a casement window on the north-facing elevation and a window (3/10) on the south-facing elevation. The interior walls are all modern. A modern 12-paned glass door allows access into the passage. A simple softwood staircase is situated on the east-facing elevation.

Interior first floor

The first floor has three rooms (Rooms 10-12) (Fig 4b). Rooms 10 and 11 have been created by the installation of a very thin stud-partition wall. Room 10 is lit by window 3/6 on the exterior north-facing elevation. Room 11 is a small box-room lit by a small window on the exterior south-facing elevation. A doorway leads off the landing into a small bathroom which included modern sanitary wares.

4.2.4 Building 4: Farmhouse

Exterior, north-facing elevation

The north-facing elevation of the farmhouse has four bays, the third bay being asymmetrical (Fig 3a, Plate 5). The building is constructed of hand-made brick using English Garden bond (5:1) resting on a foundation course of cobbles measuring 0.3m high. The windows and door (4/3, 4/4 and 4/5) are modern PVC replacements; window 4/6 is a wooden 1-over-1 sash-and-case window. On the first floor, windows 4/7 and 4/8 light the bathroom of the extension. Window 4/9 lights the staircase and is a modern PVC replacement and has a fine segmented brick arch above. The flanking windows (4/8 and 4/11) have flat arches. Between the stair window (4/9) and 4/8 is a lead insurance plaque (4/24). The skews are sandstone with moulded skewputs (4/12). The pitched roof is covered with slate (4/13). The two chimney stacks are brick-built and covered with pebble-dash render.

Exterior, south-facing elevation

The south-facing elevation of the farmhouse is covered in pebble-dash render and has three bays (Fig 3c, Plate 6). The middle bay has a door with window directly above, flanked on each side by windows at ground and first floor. The roof (4/13) is the same as on the north-facing elevation. Windows 4/21 are all the same dimension (c1.2m by 1.2m) whereas window (4/22) on the first floor above doorway 4/23 is slightly narrower (c. 1m by 1.2m). All the fenestration has raised margins of white-painted sandstone.

Exterior, west-facing gable

The west-facing gable of the farmhouse is partly rendered with pebble-dash render (4/16). The only notable feature is a sash-and-case window that is not aligned to the chimney stack (Fig 3b, Plate 7). The projecting skewput stones (4/12) are more visible on this elevation. The lower part of the elevation to the height of the window sill is masked by the rear wall of a dilapidated lean-to building (4/18). The lean-to roof

(4/20) is corrugated asbestos and has collapsed. The roof was supported by the flanking walls and two piers constructed using breeze-blocks (4/19).

Exterior, east-facing gable

The east-facing gable is featureless and is covered with pebble-dash render (4/16). The first-floor level is masked by the adjoining Building 3.

Farmhouse interior

The farmhouse occupies a four-roomed plan and has eleven individual rooms (Fig 4a-b, Plates 8-11). The core-block of the farmhouse has walls measure 0.4m thick. Internal partitions are 0.18m thick on average. The ground floor hall is staggered and it provides access to all the rooms and central staircase. Table 5 lists the dimensions of each room. Period features are a rarity and the earliest feature surviving is the staircase and the roof trusses (see below) which are all late 18th century.

On the first floor a bedroom on the north side of the building has been compartmentalised to form two bathrooms (Rooms 12 & 13). Room 13 serves the farmhouse whilst Room 12 serves the extension, Building 3.

					Digital	Photo	S
Room	Function	Dimensions (m)	Description of significant	N	E	S	W
No		(Length x width)	features/observations				
1	Living	5.4 x 4.2	A c.mid-19 th century cast-iron	001	002	003	004
	Room		horseshoe fireplace on west-				
			facing elevation. The fire-				
			surround (Plate 8) is ornate with				
			fluted in-bands and central boss.				
			A sash and case window (3-over-				
			3) is present at the centre of the				
			north- facing elevation. Moulded				
			skirting board and picture rail.				
			Built in cupboard to the right of				
			the fireplace (20 th century).				
2	Hall	12.5 x 1.5	The hall has a wooden plank floor			005	006
			(19 th century) inlaid with a lighter				
			(lime or box wood) border with				
			oak leaves (Plate 9 & 11). Rear				
			and front doors are modern PVC.				
3	Living	4.3 x 4.2	No period features. Windows are	007	008	009	010
	room		modern PVC. The fireplace is	011			
			modern.				
4	Sitting	4 x 3.9	Early 20 th century fitted pine		012	013	014
	Room		cupboards and stripped 6-panelled				
			door.				
5	Staircase	3.1 x 1.3	Fine late 18 th or early 19 th century				025
			staircase with softwood handrail				
			and square balustrades. The risers				
			are all moulded softwood (pine).				
			Built-in stair cupboard of pine.				
6	Kitchen	5.4 x 3.9	All modern fixtures and fittings.	015	016	018	019
			An original beam (0.2m x 0.2m)		017		
			is visible between a timber mock-				
			beam ceiling.				

					Digital	Photo	S
Room No	Function	Dimensions (m) (Length x width)	Description of significant features/observations	N	E	S	W
7	Passage to Room 8 and farmyard	7.2 x 1	No period fixtures or fittings.		020		021
8	Living room	5.1 x 4.5	No period fixtures of fittings.	022	023	024	025
9	Utility room	4.5 x 4	Featureless room, plank-lined ceiling. Plank-built door to outhouse on west-facing elevation.	027		026	
10	Bedroom	3.3 x 2.1	No period features, all modern.	028		029	
11	Box Room	3.2 x 1.9	No period features, all modern.	030		031	
12	Bathroom	4 x 1.6	All modern fixtures and fittings.	032		033	
13	Bathroom	4 x 2.1	All modern fixtures and fittings.	034		035	
14	Landing	5.2 x 2.4	Period (late 18 th century) landing window opening with modern PVC replacement. Period balustrade and hand rail on landing stairs (Plate 10).	040		041	
15	Bedroom	3.9 x 3.7	No period fixtures and fittings.	044		043	
16	Bedroom	4.5 x 4	Wooden sash-and-case window. A stripped 6-panelled door is present.			046 047	
17	Box room	3.4 x 2.7	No features of architectural interest.	050		049	

Table 5 Function, dimensions, observations and digital shot number in each room within the farmhouse (Building 4)

Roof truss configuration

Three king-post roof trusses are present within the roof of the farmhouse (Plate 12-13). All are dressed softwood and are peg- jointed. The purlins are trenched. Table 6 lists the principal features present on the king-post trusses.

Feature No	Description
1	Pine king post with shouldered base and soffit carrying the ridge plate (8)
2	Squared pine struts supporting the principal rafter (3)
3	Rectangular dressed principal rafters with trenches for the purlins (4)
4	Dressed pine purlins (through purlins) supporting the common rafters
5	Dressed pine common rafters supporting the sarking boards
6	Sarking boards (pine) c. 0.25m wide.
7	Timber tie-beam
8	Timber (pine) ridge plate

Table 6. Roof truss features in Building 4. Feature numbers are shown on Plate 12.

4.3 West Range

The west range incorporates Buildings 5 and 6, a brick-built threshing barn and a steel-framed workshop.

4.3.1 Building 5: Threshing Barn

The barn (Fig 5a-b) measures 11.8m by 5m. The main build (5/1) is English Garden bond (5:1) and the bricks are hand-made and share the same characteristics as the farmhouse (Building 4). The east-facing elevation of the threshing barn includes a large plank-built door (5/2) at the south end. A small window is present midway along the elevation (5/3). A large bay opening is surmounted by a timber lintel at the north end (5/4). A modern steel-framed lean-to partly hides a plank-built pitching door on the first floor (5/5).

The south-facing gable (Fig. 6a, Plate 15) is pitched and has five blocked slit vents (5/6). Six blocked slit vents are visible on the north-facing gable which has been incorporated into Building 6, the steel-framed workshop.

The west-facing elevation (Fig 5b) has two small windows (5/7) at the ground floor which are surmounted by a row of blocked slit vents (5/8). A set of four blocked vents are present at the north end of the building. Situated 8.4m from the south-gable is an out-shot blocked doorway (5/9) measuring 3m wide (Plate 14). The doorway has a cat-slide roof covered with corrugated asbestos (5/10).

Interior features

The barn has been divided in two compartments by the installation of a brick-built partition wall (late 19th century?) which runs east-west across the barn. The larger unit (8.7m by 4.8m) within the barn was formerly used as a milking parlour and still retains five milking stalls on the interior east-facing wall. At the north end the smaller unit (5.8m by 4.8m) has been converted into a grain silo and is lined with breezeblocks.

The loft floor only survives over the former milking parlour and, judging by its relationship with the iron-A-framed roof, it dates from the 20th century. The wall heads have been raised with grey brickwork to accommodate the roof, which is covered by corrugated asbestos (5/11).

4.3.2 Building 6: Steel-framed workshop

Building 6 is a steel-framed workshop measuring 10.6m by 6.4m and is open on its west-facing elevation (Fig 5a-b, 6b). The roof is corrugated steel and slopes down towards the north end. The roof is supported by steel I-beams.

4.4 North Range

The late 18th / early 19th century core of the north range also includes Buildings 8 and 11. Building 7 is probably of 19th century date whilst buildings 9, 10 and 12 are 20th century additions (Fig. 6a-b).

4.4.1 Building 7: Workshop

Building 7 is a rectangular lean-to workshop measuring 7.7m long by 2.7m wide and is constructed of machine made brick (English Garden bond 5:1) (Fig. 6a). It has been

constructed within the return angle of Building 8's doorway which has been extended southwards with brickwork. The building is accessed by a central steel doorway (5/2) on the south-facing elevation and is flanked by two windows (5/3 and 5/4). Two smaller windows are present just below eaves level (5/5 and 5/6) (Fig. 6a).

The only notable feature worthy of mention within the interior of Building 7 is its back wall which includes a blocked doorway measuring c. 1.2m high and c. 1m wide. The blocking work is brick and the same type as that used to construct Building 7. The doorway would have provided another route into Building 8. The rest of the walls are hidden behind shelving and storage bins.

4.4.2 Building 8: Burnt-out barn

Building 8 was destroyed by a major fire in 2005. The building now survives as a roofless shell and measures 14.4m by 4.8m. Its principal entrance measures 2.5m wide and is situated on the south-facing elevation facing the courtyard (Fig 6a). The outshot entrance walls survive to the full height of about 4m and these would have carried a cat-slide roof similar to that on the west-facing elevation of Building 5. The interior walls are constructed of English Garden wall bond (5.1) and the entrance wall are English Garden Bond (3:1).

The sockets for the main loft timbers are visible surmounted by a series of slit vents that occupy the full length of the rear (south-facing) elevation (Fig. 6a, Plate 16). There is also minor blocking work at the east end of the building. On the ground floor a large hole in the wall shows that the barn is constructed from a double skin wall. Several large fire-damaged oak beams still lie on the floor of the adjacent building (Building 9).

At the east end of building a brick-built partition wall has been installed to create a small animal shed which measures 4.8m by 3.2m. The shed is accessed by a doorway on the south-facing elevation.

4.4.3 Building 9: Lean-to

Building 9 is a brick-built lean-to building built against the north-facing elevation of Building 8 (Fig 6b). It measures 11m by 5.7m and was last used as a sheep shed. Access to the shed is by two large doorways on the north-facing elevation. The corrugated asbestos roof is supported by dressed timber mono-type frame trusses which are scarfe-jointed and nailed (Plate 18). The walls are whitewashed and featureless.

4.4.4 Building 10: Hay barn

Building 10 is a large timber-framed hay barn which is fully open on its north-facing elevation (Fig 6b). A series of large diameter timber posts support the corrugated iron roof. The sides of the barn are timber clad. The roof is supported by A-frame rafters that rest on a timber wall plate. The rear wall of the barn is a truncated section of an earlier wall with slit vents measuring 12.5m long and 3m high.

4.4.5 Building 11: Shed

Building 11 is 12.5m long by 5.1m wide and comprises a modern steel-framed shed used for storing farm machinery (Fig 6a-b). The building incorporates the aforementioned section of an earlier brick wall pierced by slit vents. The floor is concrete and the roof is clad with corrugated iron sheeting.

4.4.6 Building 12: Shed

Building 12 is a steel-framed lean-to implement shed with a steel clad roof (Fig 6a-b). The partition wall between Buildings 10 and 11 is built of breeze-blocks. The building was erected in the recent past and is of no historical interest.

5 DISCUSSION

5.1 Phase development

A review of the development is now considered based on the results of the standing building survey and map regression analysis. A colour-coded phase development plan is shown as Fig. 1.

Phase 1: Late 18th / early 19th century

Crindledyke Steading is a typical courtyard steading with the principal buildings arranged around the farmyard. At the core of the complex of buildings is the farmhouse and annex buildings whose present-day footprint is more or less the same as that depicted on the 1820 tithe map. The two large barns (Buildings 5 and 8) are present during this period and represent threshing barns, which commonly had an extended doorway with cheeks on either side (Brunskill 1971). Another former rectangular building was probably a byre, of which now only one wall survives, and which now forms the dividing wall between modern sheds Buildings 10 and 11.

The farmhouse king-post roof trusses appear to be contemporary with the building's core block. The three pine trusses are numbered (I II &III) and were constructed in kit form on the ground in the carpenter's workshop prior to their installation. During the 18th and 19th century king-post trusses were widely adopted and favoured for their efficiency and they are suitable for quite wide spans because the king-post itself acts to prevent the tie-beam from sagging (Harris 1978).

The staircase and possibly the squat six-panelled doors on the first floor are the only survivors from this period. The staircase is probably pine with very fine balusters, newel post and moulded risers (Plate 9, 10).

Phase 2: 19th century

Nineteenth century alterations appear to be mainly confined to the interior of the farmhouse and the core block of its annex buildings (Buildings 2 and 3), which may have replaced the earlier buildings depicted on the tithe map. The inlaid hall floor in the farmhouse, with its inlaid oak leaf border (Plate 11), is possibly inspired by the Arts and Crafts movement that flourished between 1860 and 1910. The ornate wooden fire surround in Room 1 (Plate 8) appears to be typically Edwardian with its high surround and overmantle. The cast-iron grate within is probably late 19th century and has been re-used in the later fireplace. The brass-plated fender is probably an Art Deco reproduction.

Buildings 2, 3 and 7 share the same machine-made brick and are of 19th century date.

Phase 3: 20th century

This phase has the largest number of elements and includes Building 1 and the collapsed lean-to on the west gable of Building 4. The lean-tos on the east and west side of Building 5 and the grain silo within its interior also belong to this phase. All the steel-framed sheds (Building 6, 9-12) are recent 20th century structures. Included

within this phase is the refurbishment of the farmhouse interior, with its bathroom conversions.

6. CONCLUSIONS

Three broad phases of development are proposed at High Crindledyke Farm and it is likely that there will be a certain amount of overlap within each phase.

The core block of the farmhouse has remained the same since it was constructed. The king-post roof trusses appear to be original late 18th century features, as is the farmhouse staircase. Other curiosities include the hall floor which is possibly Arts and Crafts inspired. Other period features include the Edwardian fire-surround in Room 1 on the ground floor. Apart from these, all other period features have been removed during modernisation. An upstairs bedroom has been remodelled into two bathrooms to serve the needs of the farmhouse and Building 3, the 20th century flat. The rest of the farmhouse has been modernised to suit the needs of 20th century living.

Collectively, the agricultural buildings are of historical interest as they reflect the typical changes in use from arable to pastoral use. The early 19th century was an important period, when local agricultural change affected the pattern and layout of farm buildings. During this period, dispersed rural steadings developed into smallholdings arranged around courtyards combining all the requirements for mixed farming with threshing barns, cattle courts, byres and domestic accommodation (English Heritage 2006). Twentieth-century development has also left its mark on the buildings, some of which have been modified to suit the needs of animal husbandry. Building 5, the former threshing barn, was converted into a grain silo and a milking parlour.

7. RECOMMENDATIONS

The Level 3 standing building survey has been carried out at High Crindledyke Farm and its developmental history is now understood. No further recording work is recommended prior to the farm's demolition. The decision for any further recording work in the light of the survey results lies with Cumbria County Council.

As required by Cumbria County Council, a watching brief will take place during the later stages of demolition to determine whether any earlier buildings lie below the footprint of the current buildings. The results of this work will be produced under separate cover.

8. BIBLIOGRAPHY

Brunskill, R.W 1971 'Illustrated Handbook of Vernacular Architecture', p.151.

English Heritage (2006) 'Understanding Historic Buildings: A guide to good recording practice'.

English Heritage (2006) 'The Conversion of Traditional Farm Buildings: A guide to good recording practice'.

Harris, R 1978 'Discovering Timber-framed Buildings'. p.85.

Cartographic

The Cargo Parish Tithe map and Schedule 1820

Ordnance Survey 1865 First Edition 6" to the mile Cumberland Sheet XV1

Ordnance Survey 1901 Second Edition 6" to the mile Sheet Cumberland Sheet XV1

Ordnance Survey 1926 6" to the mile Cumberland Sheet XV1.SE

Ordnance Survey 1937-1939 with additions Cumberland Sheet XV1.SE


Donald, Thomas 1774 Map of Cumberland. Produced by the Cumberland & Westmorland Antiquarian & Archaeological Society in 2002.


APPENDIX 1: Digital Photographic Register

Shot No.	Summery description of subject	Facing
001	Building 4, Room 1 south-facing elevation	North
002	Building 4, Room 1 west-facing elevation with ornate fireplace	East
003	Building 4, Room 1 north-facing window	South
004	Building 4, Room 1 east-facing elevation and entrance	West
005	Building 4, Room 2 rear doorway and hallway	South
006	Building 4, Room 2 staircase and hallway	North
007	Building 4, Room 3 south-facing elevation	North
008	Building 4, Room 3 north-facing central window	South
009	Building 4, Room 3 west-facing wall and doorway	East
010	Building 4, Room 3 east-facing modern fireplace	West
011	Building 4, Room 3 south-facing window and wall	North
012	Building 4, Room 4 west-facing doorway	East
013	Building 4, Room 4 north-facing wall and cupboards	South
014	Building 4, Room 4 east-facing modern fireplace	West
015	Building 4, Room 6 south-facing kitchen windows and worktops	North
016	Building 4, Room 6 west-facing wall and ceiling	East
017	Building 4, Room 6 west-facing wall and ceiling	East
018	Building 4, Room 6 north facing kitchen cabinet and wall	South
019	Building 4, Room 6 east-facing brick-built fireplace	West
020	Building 4, Room 7 general shot of the passage to Building 3	East
021	Building 4, Room 7 general shot of the passage to Building 3	West
022	Building 4, Room 8 south-facing wall and doorway	North
023	Building 4, Room 8 west-facing doorway and fireplace	East
024	Building 4, Room 8 north-facing casement window	South
025	Building 4, Room 8 east-facing staircase	West
026	Building 4, Room 9 utility room, general shot	South-east
027	Building 4, Room 9 utility room, general shot	North-west
028	Building 4, Room 10 south-facing window	North
029	Building 4, Room 10, featureless walls	South
030	Building 4, Room 11 south-facing doorway	North
031	Building 4, Room 11 north-facing window	South
032	Building 4, Room 12 south-facing wall, toilet and sink	North
033	Building 4, Room 12 north-facing tiled wall and bath	South
034	Building 4, Room 13south-facing window, toilet and sink	North
035	Building 4, Room 13 north-facing entrance and airing cupboard	South
036	Building 4, Room 18 south-facing bedroom wall	North
037	Building 4, Room 18 north-facing sash and case window	South
038	Building 4, Room 18 east-facing door and wall	West
039	Building 4, Room 18 west-facing built in cupboard and chimney breast	East
040	Building 4, Room 14 landing balustrade	North
041	Building 4 Room 14 staircase handrail and newal post	West
042	Building 4 Room 14 landing and staircase handrail	South
043	Building 4 Room 15 north-facing bedroom window	South
044	Building 4 Room 15 south-facing door	North
045	Building 4 Room 15 west-facing wall and doorway	North-east
046	Building 4 Room 16 south-facing wall and doorway	South
047	Building 4 Room 16 north-facing central window	South
048	Building 4 Room 16 east and south-facing windows	North-west
049	Building 4 Room 17 north-facing boxroom doorway	South
050	Building 4 Room 17 north-facing central window	North
050	Building for ground floor staircase moulded risers	West
051	Building 4, Hallway inlaid wooden floor with floral pattern border	South
052	Building 2 store shed, interior shot	North
053	Building 2 store shed, interior shot with rubble-built back wall	South

Building 1, west end store shed, door to byre South	Shot No.	Summery description of subject	Facing
South	055	Building 1, west end store shed	North
DSS	056	Building 1, west end store shed, door to byre	South-east
South	057	Building 1, west end store shed, door to byre	South
Building 1 byre, north-facing wall and roof truss O61	058	Building 1, west end store shed, chemical store	West
Building 1 byre, general shot of structural roof trusses West	059	Building 1, byre roof and steel-framed truss	South
Building 1 byre, west-facing interior bay opening on east gable East	060	Building 1 byre, north-facing wall and roof truss	South-west
Building 5 north-facing interior gable wall and loft floor South	061	Building 1 byre, general shot of structural roof trusses	West
Building 5 general shot of the roof truss	062	Building 1 byre, west-facing interior bay opening on east gable	East
Description	063	Building 5 north-facing interior gable wall and loft floor	South
December 2009 Building 5 south-facing interior gable and grain silo crusher North-067 Building 5 interior north end, silo floor North-068 Building 5 seast-facing interior wall, general shot West	064	Building 5 general shot of the roof truss	South
067 Building 5 interior north end, silo floor North-w 068 Building 5 east-facing interior wall, general shot West 069 Building 7 south-facing interior wall with earlier floor joist sockets South 070 Building 7 west-facing interior gable wall East 071 Building 7 west-facing wall and loft window South 072 Building 7 east-facing wall and loft window South 073 Building 7 east-facing wall and door to modern workshop West 074 Building 5 lower section of the south gable below lean-to shed North 075 Building 5 upper section of the south-facing gable North 076 Building 5 west-facing elevation consecutive overlapping shots East 098-122 Building 8 +12, north range, overlapping consecutive shots East 193-123 Building 4, gable and lean-to, consecutive shots East 142 Building 5, general shot of the west-facing gable East 143 Building 5, general shot of the south-facing gable North-ea 144 Building 5, general shot of the south-facing gable North-ea 189-190 B	065	Building 5 east-facing interior blocked barn doorway	East
068	066	Building 5 south-facing interior gable and grain silo crusher	North
069 Building 5 west-facing interior wall with earlier floor joist sockets South 070 Building 7 south-facing wall of workshop with blocking work North 071 Building 7 west-facing wall and loft window South 072 Building 7 west-facing wall and loft window South 073 Building 7 east-facing wall and door to modern workshop West 074 Building 5 lower section of the south gable below lean-to shed North 075 Building 5 lower section of the south-facing gable North 076 Building 5 west-facing elevation consecutive overlapping shots East 077-097 Building 8-12, north range, overlapping consecutive shots South 123-141 Building 8, gable and lean-to, consecutive shots East 142 Building 4, gable and lean-to, consecutive shots East 143 Building 5, general shot of the west-facing gable East 144 Building 5, general shot of the south-facing gable North 145-169 North-range, south-facing elevation, Buildings 12, 11, 8, and 7, consecutive shots West 189-190 Building 4, farmhouse, south-facing elevation North <td>067</td> <td>Building 5 interior north end, silo floor</td> <td>North-west</td>	067	Building 5 interior north end, silo floor	North-west
070 Building 7 west-facing wall of workshop with blocking work North 071 Building 7 west-facing interior gable wall East 072 Building 7 north-facing wall and loft window South 073 Building 5 north-facing wall and door to modern workshop West 074 Building 5 lower section of the south gable below lean-to shed North 075 Building 5 upper section of the south-facing gable North 076 Building 5 with modern steel-framed shed on west side North 077-097 Building 5 west-facing elevation consecutive overlapping shots East 098-122 Building 8-12, north range, overlapping consecutive shots South 123-141 Building 4, gable and lean-to, consecutive shots East 142 Building 4, general shot of the west-facing gable East 143 Building 5, general shot of the south-facing gable North-ea 144 Building 5, general shot of the south-facing gable North-ea 144 Building 5, general shot of the south-facing gable North-ea 145-169 North-range, south-facing elevation, Buildings 12, 11, 8, and 7, North-ea	068	Building 5 east-facing interior wall, general shot	West
071 Building 7 north-facing wall and loft window South 072 Building 7 north-facing wall and door to modern workshop West 073 Building 7 east-facing wall and door to modern workshop West 074 Building 5 lower section of the south gable below lean-to shed North 075 Building 5 upper section of the south-facing gable North 076 Building 5 with modern steel-framed shed on west side North 077-097 Building 5 west-facing elevation consecutive shots East 098-122 Building 4, gable and lean-to, consecutive shots East 142 Building 4, general shot of the west-facing gable East 143 Building 5, general shot of the south-facing gable North-real 144 Building 5, general shot of the south-facing gable North-real 144 Building 5, general shot of the south-facing gable North-real 144 Building 5, general shot of the south-facing gable North-real 144 Building 4, garnhouse gable and lean-to, shot North-real 145-169 North-range, south-facing elevation, Buildings 12, 11, 8, and 7, consecutive shots West	069	Building 5 west-facing interior wall with earlier floor joist sockets	South
071 Building 7 north-facing wall and loft window South 072 Building 7 north-facing wall and loft window South 073 Building 7 east-facing wall and door to modern workshop West 074 Building 5 lower section of the south gable below lean-to shed North 075 Building 5 upper section of the south-facing gable North 076 Building 5 with modern steel-framed shed on west side North 077-097 Building 5 west-facing elevation consecutive source steel North 077-097 Building 4, gable and lean-to, consecutive shots East 108-122 Building 4, gable and lean-to, consecutive shots East 142 Building 4, general shot of the west-facing gable East 143 Building 5, general shot of the south-facing gable North-reapt 144 Building 5, general shot of the south-facing gable North-reapt 144 Building 5, general shot of the south-facing gable North-reapt 144 Building 4, garnal shot North-see 170-188 East range, Building 5, consecutive shots West 189-190 Building 4, farmhouse gabl	070	Building 7 south-facing wall of workshop with blocking work	North
Building 7 east-facing wall and door to modern workshop West	071		East
Building 7 east-facing wall and door to modern workshop West	072		
074 Building 5 lower section of the south gable below lean-to shed North 075 Building 5 upper section of the south-facing gable North 076 Building 5 with modern steel-framed shed on west side North 077-097 Building 5 west-facing elevation consecutive overlapping shots East 098-122 Building 4, gable and lean-to, consecutive shots South 123-141 Building 4, general shot of the west-facing gable East 142 Building 5, general shot of the south-facing gable North-ea 144 Building 5, general shot of the south-facing gable North 144 Building 5, general shot of the south-facing gable North 144 Building 4, general shot of the south-facing gable North 145-169 North-range, south-facing elevation, Buildings 12, 11, 8, and 7, consecutive shots West 170-188 East range, Building 5, consecutive shots West 189-190 Building 4 farmhouse, south-facing elevation North 191 Building 4 farmhouse gable and adjoining lean-to shed North 222 Building 4, 3 and 2 consecutive shots from the west to east North	073		
D75 Building 5 upper section of the south-facing gable North	074		North
076 Building 5 with modern steel-framed shed on west side North 077-097 Building 5 west-facing elevation consecutive overlapping shots East 098-122 Building 4, gable and lean-to, consecutive shots South 123-141 Building 4, gable and lean-to, consecutive shots East 142 Building 4, general shot of the west-facing gable North-read 144 Building 5, general shot of the south-facing gable North-read 145-169 North-range, south-facing elevation, Buildings 12, 11, 8, and 7, consecutive shots North 170-188 East range, Building 5, consecutive shots West 189-190 Building 4, farmhouse, south-facing elevation North 191 Building 4, 3 and 2 consecutive shots from the west to east North 192-222 Building 4, 3 and 2 consecutive shots from the west to east East 223 Rear wall of Building 1 and 2 junction hidden behind a modern shed East 224-235 Building 2, rear wall with brick and cobble build North 236 Topographic shot of Crindledyke Farm North-w 237-238 Topographic shot of Crindledyke Farm North-w			
077-097 Building 5 west-facing elevation consecutive overlapping shots East 098-122 Building 8-12, north range, overlapping consecutive shots South 123-141 Building 4, gable and lean-to, consecutive shots East 142 Building 4, general shot of the west-facing gable East 143 Building 5, general shot North-ea 144 Building 5, general shot of the south-facing gable North 145-169 North-range, south-facing elevation, Buildings 12, 11, 8, and 7, consecutive shots West 170-188 East range, Building 5, consecutive shots West 189-190 Building 4, farmhouse, south-facing elevation North 191 Building 4, farmhouse gable and adjoining lean-to shed North 192-222 Building 4, 3 and 2 consecutive shots from the west to east North 192-222 Building 2, rear wall with brick and cobble build North 236 Topographic shot of Crindledyke Farm North-w 237-238 Topographic shot of Crindledyke Farm North-w 239-247 Building 4, farmhouse king-post roof trusses East & West 250-251 <td< td=""><td>076</td><td></td><td>North</td></td<>	076		North
098-122 Building 8-12, north range, overlapping consecutive shots South 123-141 Building 4, gable and lean-to, consecutive shots East 142 Building 4, general shot of the west-facing gable East 143 Building 5, general shot of the south-facing gable North-range, south-facing elevation, Buildings 12, 11, 8, and 7, consecutive shots North 144 Building 5, general shot of the south-facing gable North 170-188 East range, Building 5, consecutive shots West 189-190 Building 4 farmhouse, south-facing elevation North 191 Building 4 farmhouse, south-facing elevation North 192-222 Building 4, 3 and 2 consecutive shots from the west to east North 192-221 Building 4, 3 and 2 consecutive shots from the west to east North 223 Rear wall of Building 1 and 2 junction hidden behind a modern shed East 224-235 Building 8, rear wall with brick and cobble build North 236 Topographic shot of Crindledyke Farm North-we 237-238 Topographic shot of Crindledyke Farm North-we 239-247 Building 4, farmhouse roof trusses and pur	077-097	<u> </u>	
142 Building 4, general shot of the west-facing gable East 143 Building 5, general shot North-ea 144 Building 5, general shot of the south-facing gable North 145-169 North-range, south-facing elevation, Buildings 12, 11, 8, and 7, consecutive shots West 170-188 East range, Building 5, consecutive shots West 189-190 Building 4, farmhouse, south-facing elevation North 191 Building 4 farmhouse gable and adjoining lean-to shed North 192-222 Building 4, 3 and 2 consecutive shots from the west to east North 223 Rear wall of Building 1 and 2 junction hidden behind a modern shed East 224-235 Building 2, rear wall with brick and cobble build North 236 Topographic shot of Crindledyke Farm North-w 237-238 Topographic shot of Crindledyke Farm North-w 239-247 Building 4, farmhouse king-post roof trusses East & 248-249 Building 4, farmhouse roof trusses and purlins West 250-251 Building 4, King-post, general shot West 255 Building 4, sarking boards and purlins West 255 Buildi	098-122		
142 Building 4, general shot of the west-facing gable East 143 Building 5, general shot North-ea 144 Building 5, general shot of the south-facing gable North 145-169 North-range, south-facing elevation, Buildings 12, 11, 8, and 7, consecutive shots West 170-188 East range, Building 5, consecutive shots West 189-190 Building 4, farmhouse, south-facing elevation North 191 Building 4 farmhouse gable and adjoining lean-to shed North 192-222 Building 4, 3 and 2 consecutive shots from the west to east North 223 Rear wall of Building 1 and 2 junction hidden behind a modern shed East 224-235 Building 2, rear wall with brick and cobble build North 236 Topographic shot of Crindledyke Farm North-w 237-238 Topographic shot of Crindledyke Farm North-w 239-247 Building 4, farmhouse king-post roof trusses East & West 248-249 Building 4, farmhouse roof trusses and purlins West 250-251 Building 4, King-post, general shot West 253-254 Building 4, King-post seat and tie beam West 255-258	123-141		
Building 5, general shot North-earth	142		
144 Building 5, general shot of the south-facing gable North 145-169 North-range, south-facing elevation, Buildings 12, 11, 8, and 7, consecutive shots 170-188 East range, Building 5, consecutive shots West 189-190 Building 4, farmhouse, south-facing elevation North 191 Building 4 farmhouse gable and adjoining lean-to shed North 192-222 Building 4, 3 and 2 consecutive shots from the west to east North 192-223 Rear wall of Building 1 and 2 junction hidden behind a modern shed East 224-235 Building 2, rear wall with brick and cobble build North 236 Topographic shot of Crindledyke Farm North-wall 237-238 Topographic shot of Crindledyke Farm North-wall 239-247 Building 4, farmhouse king-post roof trusses East & West 248-249 Building 4, farmhouse, roof sarking boards West 250-251 Building 4, farmhouse roof trusses and purlins West 253-254 Building 4, King-post seat and tie beam West 253-254 Building 4, King-post seat and tie beam West 257-258 Building 4, sarking boards and purlins West 257-258 Building 5, south end of barn below lean-to shed West 259-260 Building 8, south facing interior wall of the burnt-out barn North-wall 261 Building 8, former doorway on south elevation South-east 262 Building 8, former doorway on south elevation South-east 263 Building 11, interior east-facing gable with wide bay opening West 269 Small animal house built on the east end of Building 8 North North-wall 269 Small animal house built on the east end of Building 8 North North 269 Small animal house built on the east end of Building 8 North North 269 Small animal house built on the east end of Building 8 North North 269 Small animal house built on the east end of Building 8 North North 269 Small animal house built on the east end of Building 8 North North 269 Small animal house built on the east end of Building 8 North North 269 Small animal house built	143		North-east
North-range, south-facing elevation, Buildings 12, 11, 8, and 7, consecutive shots	144		
170-188East range, Building 5, consecutive shotsWest189-190Building 4, farmhouse, south-facing elevationNorth191Building 4 farmhouse gable and adjoining lean-to shedNorth192-222Building 4, 3 and 2 consecutive shots from the west to eastNorth223Rear wall of Building 1 and 2 junction hidden behind a modern shedEast224-235Building 2, rear wall with brick and cobble buildNorth236Topographic shot of Crindledyke FarmNorth-w237-238Topographic shot of Crindledyke FarmNorth-w239-247Building 4, farmhouse king-post roof trussesEast & West248-249Building 4, farmhouse, roof sarking boardsWest250-251Building 4, farmhouse roof trusses and purlinsWest252Building 4, King-post, general shotWest253-254Building 4, King-post seat and tie beamWest255Building 3, south end of barn below lean-to shedWest257-258Building 5, south end of barn below lean-to shedWest259-260Building 8, south facing interior wall of the burnt-out barnNorth-w261Building 8, west-facing gable end (remains of)East262Building 8, former doorway on south elevationSouth-ea263Building 11, interior east-facing wallWest265-267Building 11, interior south-facing truncated wall with slit ventsNorth268Building 1, east-facing gable with wide bay openingWest269Small animal house built on the east end of Buildi	145-169		North
189-190Building 4, farmhouse, south-facing elevationNorth191Building 4 farmhouse gable and adjoining lean-to shedNorth192-222Building 4, 3 and 2 consecutive shots from the west to eastNorth223Rear wall of Building 1 and 2 junction hidden behind a modern shedEast224-235Building 2, rear wall with brick and cobble buildNorth236Topographic shot of Crindledyke FarmNorth-w237-238Topographic shot of Crindledyke FarmNorth-w239-247Building 4, farmhouse king-post roof trussesEast & West248-249Building 4, farmhouse, roof sarking boardsWest250-251Building 4, farmhouse roof trusses and purlinsWest252Building 4, King-post, general shotWest253-254Building 4, King-post seat and tie beamWest255Building 4, sarking boards and purlinsWest256Building 5, south end of barn below lean-to shedWest257-258Building 7, on north range, general shotNorth-w261Building 8, south facing interior wall of the burnt-out barnNorth261Building 8, west-facing gable end (remains of)East262Building 8, eastern side of the doorway with former cat-slide roofSouth-ea264Building 11, interior east-facing wallWest265-267Building 11, interior south-facing truncated wall with slit ventsNorth268Building 11, east-facing gable with wide bay openingWest269Small animal house built on the east end of Bu	170-188		West
Building 4 farmhouse gable and adjoining lean-to shed North			
192-222 Building 4, 3 and 2 consecutive shots from the west to east North			
223Rear wall of Building 1 and 2 junction hidden behind a modern shedEast224-235Building 2, rear wall with brick and cobble buildNorth236Topographic shot of Crindledyke FarmNorth-w237-238Topographic shot of Crindledyke FarmNorth-w239-247Building 4, farmhouse king-post roof trussesEast & West248-249Building 4, farmhouse, roof sarking boardsWest250-251Building 4, farmhouse roof trusses and purlinsWest252Building 4, King-post, general shotWest253-254Building 4, King-post seat and tie beamWest255Building 5, south end of barn below lean-to shedWest257-258Building 5, south end of barn below lean-to shedWest259-260Building 8, south facing interior wall of the burnt-out barnNorth-w261Building 8, west-facing gable end (remains of)East262Building 8, former doorway on south elevationSouth-ea263Building 8, eastern side of the doorway with former cat-slide roofSouth-ea264Building 11, interior east-facing wallWest265-267Building 11, interior south-facing truncated wall with slit ventsNorth268Building 1, east-facing gable with wide bay openingWest269Small animal house built on the east end of Building 8North			
224-235Building 2, rear wall with brick and cobble buildNorth236Topographic shot of Crindledyke FarmNorth237-238Topographic shot of Crindledyke FarmNorth-w239-247Building 4, farmhouse king-post roof trussesEast & West248-249Building 4, farmhouse, roof sarking boardsWest250-251Building 4, farmhouse roof trusses and purlinsWest252Building 4, King-post, general shotWest253-254Building 4, King-post seat and tie beamWest255Building 5, south end of barn below lean-to shedWest257-258Building 7, on north range, general shotNorth-w259-260Building 8, south facing interior wall of the burnt-out barnNorth261Building 8, west-facing gable end (remains of)East262Building 8, former doorway on south elevationSouth-ea263Building 8, eastern side of the doorway with former cat-slide roofSouth-ea264Building 11, interior east-facing wallWest265-267Building 11, interior south-facing truncated wall with slit ventsNorth268Building 1, east-facing gable with wide bay openingWest269Small animal house built on the east end of Building 8North			
236Topographic shot of Crindledyke FarmNorth237-238Topographic shot of Crindledyke FarmNorth-w239-247Building 4, farmhouse king-post roof trussesEast & West248-249Building 4, farmhouse, roof sarking boardsWest250-251Building 4, farmhouse roof trusses and purlinsWest252Building 4, King-post, general shotWest253-254Building 4, King-post seat and tie beamWest255Building 4, sarking boards and purlinsWest256Building 5, south end of barn below lean-to shedWest257-258Building 7, on north range, general shotNorth-w259-260Building 8, south facing interior wall of the burnt-out barnNorth261Building 8, west-facing gable end (remains of)East262Building 8, former doorway on south elevationSouth263Building 8, eastern side of the doorway with former cat-slide roofSouth-ea264Building 11, interior east-facing wallWest265-267Building 11, interior south-facing truncated wall with slit ventsNorth268Building 1, east-facing gable with wide bay openingWest269Small animal house built on the east end of Building 8North			
237-238Topographic shot of Crindledyke FarmNorth-w239-247Building 4, farmhouse king-post roof trussesEast & West248-249Building 4, farmhouse, roof sarking boardsWest250-251Building 4, farmhouse roof trusses and purlinsWest252Building 4, King-post, general shotWest253-254Building 4, King-post seat and tie beamWest255Building 4, sarking boards and purlinsWest256Building 5, south end of barn below lean-to shedWest257-258Building 7, on north range, general shotNorth-w259-260Building 8, south facing interior wall of the burnt-out barnNorth261Building 8, west-facing gable end (remains of)East262Building 8, former doorway on south elevationSouth-ea263Building 8, eastern side of the doorway with former cat-slide roofSouth-ea264Building 11, interior east-facing wallWest265-267Building 11, interior south-facing truncated wall with slit ventsNorth268Building 1, east-facing gable with wide bay openingWest269Small animal house built on the east end of Building 8North			
Building 4, farmhouse king-post roof trusses 248-249 Building 4, farmhouse, roof sarking boards 250-251 Building 4, farmhouse roof trusses and purlins West 252 Building 4, King-post, general shot West 253-254 Building 4, King-post seat and tie beam West 255 Building 4, sarking boards and purlins West 256 Building 5, south end of barn below lean-to shed West 257-258 Building 7, on north range, general shot North-w 259-260 Building 8, south facing interior wall of the burnt-out barn North 261 Building 8, west-facing gable end (remains of) East 262 Building 8, former doorway on south elevation South 263 Building 8, eastern side of the doorway with former cat-slide roof South-ea 264 Building 11, interior east-facing wall West 265-267 Building 1, east-facing gable with wide bay opening West North West Small animal house built on the east end of Building 8 North			North-west
248-249Building 4, farmhouse, roof sarking boardsWest250-251Building 4, farmhouse roof trusses and purlinsWest252Building 4, King-post, general shotWest253-254Building 4, King-post seat and tie beamWest255Building 4, sarking boards and purlinsWest256Building 5, south end of barn below lean-to shedWest257-258Building 7, on north range, general shotNorth-w259-260Building 8, south facing interior wall of the burnt-out barnNorth261Building 8, west-facing gable end (remains of)East262Building 8, former doorway on south elevationSouth-ea263Building 8, eastern side of the doorway with former cat-slide roofSouth-ea264Building 11, interior east-facing wallWest265-267Building 11, interior south-facing truncated wall with slit ventsNorth268Building 1, east-facing gable with wide bay openingWest269Small animal house built on the east end of Building 8North			
248-249Building 4, farmhouse, roof sarking boardsWest250-251Building 4, farmhouse roof trusses and purlinsWest252Building 4, King-post, general shotWest253-254Building 4, King-post seat and tie beamWest255Building 4, sarking boards and purlinsWest256Building 5, south end of barn below lean-to shedWest257-258Building 7, on north range, general shotNorth-w259-260Building 8, south facing interior wall of the burnt-out barnNorth261Building 8, west-facing gable end (remains of)East262Building 8, former doorway on south elevationSouth263Building 8, eastern side of the doorway with former cat-slide roofSouth-ea264Building 11, interior east-facing wallWest265-267Building 11, interior south-facing truncated wall with slit ventsNorth268Building 1, east-facing gable with wide bay openingWest269Small animal house built on the east end of Building 8North	237 217	Building 1, furnificate king post fool trasses	
250-251Building 4, farmhouse roof trusses and purlinsWest252Building 4, King-post, general shotWest253-254Building 4, King-post seat and tie beamWest255Building 4, sarking boards and purlinsWest256Building 5, south end of barn below lean-to shedWest257-258Building 7, on north range, general shotNorth-w259-260Building 8, south facing interior wall of the burnt-out barnNorth261Building 8, west-facing gable end (remains of)East262Building 8, former doorway on south elevationSouth263Building 8, eastern side of the doorway with former cat-slide roofSouth-ea264Building 11, interior east-facing wallWest265-267Building 11, interior south-facing truncated wall with slit ventsNorth268Building 1, east-facing gable with wide bay openingWest269Small animal house built on the east end of Building 8North	248-249	Building 4, farmhouse, roof sarking boards	
252 Building 4, King-post, general shot 253-254 Building 4, King-post seat and tie beam West 255 Building 4, sarking boards and purlins West 256 Building 5, south end of barn below lean-to shed West 257-258 Building 7, on north range, general shot North-w 259-260 Building 8, south facing interior wall of the burnt-out barn North Building 8, west-facing gable end (remains of) East 262 Building 8, former doorway on south elevation South 263 Building 8, eastern side of the doorway with former cat-slide roof South-ea 264 Building 11, interior east-facing wall West 265-267 Building 11, interior south-facing truncated wall with slit vents North South S		<u> </u>	
253-254Building 4, King-post seat and tie beamWest255Building 4, sarking boards and purlinsWest256Building 5, south end of barn below lean-to shedWest257-258Building 7, on north range, general shotNorth-w259-260Building 8, south facing interior wall of the burnt-out barnNorth261Building 8, west-facing gable end (remains of)East262Building 8, former doorway on south elevationSouth263Building 8, eastern side of the doorway with former cat-slide roofSouth-ea264Building 11, interior east-facing wallWest265-267Building 11, interior south-facing truncated wall with slit ventsNorth268Building 1, east-facing gable with wide bay openingWest269Small animal house built on the east end of Building 8North		U 1	
255Building 4, sarking boards and purlinsWest256Building 5, south end of barn below lean-to shedWest257-258Building 7, on north range, general shotNorth-w259-260Building 8, south facing interior wall of the burnt-out barnNorth261Building 8, west-facing gable end (remains of)East262Building 8, former doorway on south elevationSouth263Building 8, eastern side of the doorway with former cat-slide roofSouth-ea264Building 11, interior east-facing wallWest265-267Building 11, interior south-facing truncated wall with slit ventsNorth268Building 1, east-facing gable with wide bay openingWest269Small animal house built on the east end of Building 8North			
256Building 5, south end of barn below lean-to shedWest257-258Building 7, on north range, general shotNorth-w259-260Building 8, south facing interior wall of the burnt-out barnNorth261Building 8, west-facing gable end (remains of)East262Building 8, former doorway on south elevationSouth263Building 8, eastern side of the doorway with former cat-slide roofSouth-ea264Building 11, interior east-facing wallWest265-267Building 11, interior south-facing truncated wall with slit ventsNorth268Building 1, east-facing gable with wide bay openingWest269Small animal house built on the east end of Building 8North			
257-258Building 7, on north range, general shotNorth-w259-260Building 8, south facing interior wall of the burnt-out barnNorth261Building 8, west-facing gable end (remains of)East262Building 8, former doorway on south elevationSouth263Building 8, eastern side of the doorway with former cat-slide roofSouth-ea264Building 11, interior east-facing wallWest265-267Building 11, interior south-facing truncated wall with slit ventsNorth268Building 1, east-facing gable with wide bay openingWest269Small animal house built on the east end of Building 8North			
259-260Building 8, south facing interior wall of the burnt-out barnNorth261Building 8, west-facing gable end (remains of)East262Building 8, former doorway on south elevationSouth263Building 8, eastern side of the doorway with former cat-slide roofSouth-ea264Building 11, interior east-facing wallWest265-267Building 11, interior south-facing truncated wall with slit ventsNorth268Building 1, east-facing gable with wide bay openingWest269Small animal house built on the east end of Building 8North		ŭ i	North-west
261Building 8, west-facing gable end (remains of)East262Building 8, former doorway on south elevationSouth263Building 8, eastern side of the doorway with former cat-slide roofSouth-ea264Building 11, interior east-facing wallWest265-267Building 11, interior south-facing truncated wall with slit ventsNorth268Building 1, east-facing gable with wide bay openingWest269Small animal house built on the east end of Building 8North			
262Building 8, former doorway on south elevationSouth263Building 8, eastern side of the doorway with former cat-slide roofSouth-ea264Building 11, interior east-facing wallWest265-267Building 11, interior south-facing truncated wall with slit ventsNorth268Building 1, east-facing gable with wide bay openingWest269Small animal house built on the east end of Building 8North			
263Building 8, eastern side of the doorway with former cat-slide roofSouth-ea264Building 11, interior east-facing wallWest265-267Building 11, interior south-facing truncated wall with slit ventsNorth268Building 1, east-facing gable with wide bay openingWest269Small animal house built on the east end of Building 8North			
264Building 11, interior east-facing wallWest265-267Building 11, interior south-facing truncated wall with slit ventsNorth268Building 1, east-facing gable with wide bay openingWest269Small animal house built on the east end of Building 8North		· · ·	South-east
265-267Building 11, interior south-facing truncated wall with slit ventsNorth268Building 1, east-facing gable with wide bay openingWest269Small animal house built on the east end of Building 8North		<u> </u>	
268Building 1, east-facing gable with wide bay openingWest269Small animal house built on the east end of Building 8North		- -	
269 Small animal house built on the east end of Building 8 North		<u> </u>	
<u> </u>			
Dast		-	
271 Small animal house built on the east end of Building 8 South		-	

Shot No.	Summery description of subject	Facing
272	Small animal house built on the east end of Building 8	West
273	Lean to building with Building 5 behind it	West
274	Building 8, east end following removal of fuel tanks	North
275	Building 5 south end, red-painted plank-built doorway to former milking parlour	West
276	Building 4, north-facing elevation	South
277-278	Building 9 interior south-facing wall	North
279	Building 9 interior west-facing gable	East
280	Building 9 interior north-facing collapsed wall	South
281	Building 9 interior east-facing gable wall	West
282	Building 9, mono timber roof truss	East
283	Building 9 interior, collapsed north wall	South
284-285	Building 5, east-facing interior walls with windows	West
286	Building 5, interior stalling on rear east-facing wall	West
287	Building 5 interior south-facing wall	North
288	Building 5 interior west-facing wall with plank-built door	East
289-316	Building 1-4 consecutive shots taken from east to west	South










Fig. 2b - Ordnance Survey 1st Edition Map, 1865




Fig. 2c - Ordnance Survey 1939 revised map



Key:



Revision:

Historical Map Regression

High Crindledyke Farm, Carlisle, Cumbria

Scale at A3:


NTS



Story Homes












Fig. 4a - Farmhouse, South Range, Ground Floor Plan




Fig. 4b - Farmhouse, South Range, First Floor Plan



CFA ARCHAEOLOGY LTI The Old Engine House Eskmills Park


Revision: A

Farmhouse Floor Plans

High Crindledyke Farm, Carlisle, Cumbria

Client: Story Homes

Scale at A3: 1:100










Plate 1 - East-facing entrance to Building 1



Plate 2 - Interior of building 1 showing the steel roof trusses



Plate 3 - Part of the north-facing elevation of the South Range showing Buildings 1-3



Plate 4 - South-facing elevation of Buildings 2 and 3

Key:	Fig. No: Title:	Title:				ARCHAEOLC ARCHAEOLC	The C Eskm Muss East t: 013 f: 013 e: infic	ARCHAEOLOGY LTD Jold Engine House lills Park Jelburgh Lothian, Eh21 7PQ 31 273 4390 31 273 4390 31 273 4390 31 6273 4381
	High Cri	indledyke F	arm,	Carlisle, Cumbria		Drawn by:	Checked:	Report No: 1973





Plate 5 - North-facing elevation of the farmhouse



Plate 6 - South-facing elevation of the farmhouse



Plate 7 - West-facing gable of the farmhouse

Key:	Fig. No:	A Story Homes				CFA ARCHAE The Old Engine Eskmils Park Musselburgin East Lothain, B t: 0131 273 438		
	Project:			ARCHAEOLOGY LTD e: info@cfa-archaeology.co.uk w: www.cfa-archaeology.co.uk				
	High Cri	indledyke F	arm,	Carlisle, Cumbria	Drawn by:	Checked:	Report No: 1973	





Plate 8 - Room 1 fireplace



Plate 9 - Staircase and hall



Plate 10 - Staircase and landing



Plate 11 - Ornate hall floor possibly inspired by Arts and Crafts movement

Drawn by:

Checked:

Fig. No: Revision: Key: CFA ARCHAEOLOGY LTD Story Homes The Old Engine House Eskmills Park Musselburgh East Lothian, Eh21 7PQ Title: t: 0131 273 4380 0131 273 4381 Project: Report No: 1973 High Crindledyke Farm, Carlisle, Cumbria





Plate 12 - King-post roof truss, feature descriptions listed are in Table 4




Plate 13 - The base of the king-post truss showing carpenters kit numbers

Title:				Muss East t: 013 f: 013	nills Park selburgh Lothian, En21 7PQ 31 273 4380 31 273 4381 io@cfa-archaeology.co.uk
'	rindledyke F	arm, Carlisle, Cumbria	Drawn by:		ww.cfa-archaeology.co.uk Report No: 1973





Plate 14 - West-facing elevation of Building 5, showing blocked doorway




Plate 15 - South-facing gable of Building 5 showing blocked slit vents

Кеу:	Fig. No:	Revision: A	Client: Story Homes			ARCHAEOLOGY LTD Old Engine House
	Title:				Muss	nills Park selburgh Lothian, Eh21 7PQ
	Project:			ARCHAEOLO	f: 013 e: info	31 273 4380 31 273 4381 io@cfa-archaeology.co.uk
	High Cri	indledyke F	arm, Carlisle, Cumbria	Drawn by:	Checked:	Report No:





Plate 16 - South-facing elevation of Building 8



Plate 17 - Interior of Building 8



Plate 18 - Timber mono roof in Building 9

Key:	Fig. No: Title:	A Story Homes			The C Eskm Muss East	CFA ARCHAEOLOGY LTD The Old Engine House Eskmills Park Musselburgh East Lothian, Eh21 7PQ tt: 0131 273 4380	
	Project:	,			f: 013 e: info	31 273 4381 fo@cfa-archaeology.co.uk www.cfa-archaeology.co.uk	
	High C	rindledyke F	arm, Carlisle, Cumbria	Drawn by:	Checked:	Report No: 1973	