

Photo 1: The barn, from the south-east (with roof covering exposed)



Photo 2: The barn, from the south-east




Photo 3: The earlier part of the barn, from the south-west



Photo 4: The barn, from the south-west



Photo 5: The stable and gateway, from the south-east



Photo 6: General view of the site, from the east



Photo 7: Gateway at west side, from the south



Photo 9: The barn, from the north-west



Photo 11: Barn porch, from the south-east




Photo 13: Detail of chamfered doorway to shippon in barn



Photo 14: South side of barn to east of porch, showing row of blocked breathers



Photo 16: The east gable



Photo 17: The barn, from the north-east




Photo 18: Detail of former doorway in north elevation



Photo 19: Window in north elevation of barn



Photo 20: View into barn porch and threshing floor, from the south-east






Photo 21: View into barn porch, from the south-west



Photo 22: Stone lintels of barn entrance and purlins of porch roof



Photo 25: Vertical view of threshing floor, from the west



Photo 26: Former doorway in north side of threshing bay