



Photo 23: North corner of wheel-house, with bank of pond dam at foot



Photo 24: Interior of wheel-house, from the north-west





Photo 25: North-west end of infilled wheel-pit



Photo 26: Stone block with embedded bolts at north-west end of wheel-pit





Photo 27: Stone block and timber beams spanning north-west end of wheel-house



Photo 28: Front of added store at north-west end of main building





Photo 29: Rear of added store at north-west end of main building



Photo 30: Pegged oak roof truss in added store





Photo 31: Added store at south-east end



Photo 33: Door to added store at south-east end



Photo 32: Side elevation of added store at south-east end



Photo 34: Re-used stone in stile at west corner of building