



Photo 25: First floor: north end of spine beam, resting on tie beam of truss, with pegs and numbering of struts to each side



Photo 26: Wattle and daub infill, within truss forming north side of no.247



Photo 27: Detail of wind brace on east side of truss, and scarf joint in chamfered purlin



Photo 28: Collar and ridge of truss forming north side of no.247



Photo 29: East wing: chimney stack and rear part (no.246), from the south-east



Photo 30: Chimney and roof of east wing, from the east



Photo 31: Detail of stonework forming the south side of the chimney to the east wing




Photo 32: Detail of fireplace





Photo 33: Ground floor room of no 247, from the south-west



Photo 34: Detail of post and stud at north-east corner of ground floor



Photo 35: First floor: timber framing at south-east corner, the chimney stack to the left



Photo 36: First floor: south side of main room



Photo 37: First floor: internal view of south-east wall post



Photo 38: Ground floor room of no 247, from the north-east



Photo 39: First floor: internal view of west wall plate, showing slot at left and joint with wall post at right



Photo 40: First floor: internal view of south-west wall post





Photo 41: Ground floor room of no 247, from the north-west



Photo 42: Detail of stone plinth and remnant of sill beam at south-east corner of ground floor



Photo 43: First floor: spine beam and ceiling joists over main room, from the south-east



Photo 44: Portion of wattle and daub, removed from ceiling over first floor



Photo 45: Detail of joists over ground floor room



Photo 46: Detail of floor boards exposed in rear bedroom on first floor



Photo 47: First floor: north-west corner of main room, showing spine beam and 19th century door



Photo 48: Detail of construction and furniture of 19th century door to main bedroom