

Plates



1. Stone warehouse, west-south-west elevation



2. Stone warehouse and wharfingers cottage, north-east elevation



3. Stone warehouse, north-east elevation



4. Stone warehouse, south-east elevation



5. Tunnel portal, south-east end



6. Plymcot, former Plymouth Inn coaching house and stables, north-east elevation



7. Plymcot retaining wall, view north-west



8. Plymcot retaining wall and site of former stables and closet, view east-south-east



9. Plymouth House, south-west elevation



10. Superintendent's house, north-east elevation



11. Tug Row, north-east elevation



12. Former weigh house, 1, New Wharf Cottages, and site of weighbridge, south-east elevation



13. 2, New Wharf Cottages, south-east elevation



14. 3, New Wharf Cottages, south-east elevation



15. 4, New Wharf Cottages, south-east elevation



16. 5, New Wharf Cottages, south-east elevation



17. Canal basin and Sharpness New Docks workshop, south-west elevation



18. Sharpness New Docks workshop, north-east elevation



19. Sharpness New Docks workshop, north-east elevation, south-east side



20. Sharpness New Docks workshop, north-east elevation, north-west side



21. Sharpness New Docks blacksmith's shop, south-east elevation



22. Sharpness New Docks workshop/office, view north



23. 1953 crane, view south-east



24. Canal sluice arm and wooden workshop, view north-east



25. Wooden workshop, north-east elevation



26. Brick workshops, north-east elevation



27. Lime kiln bank, general south-east view of bank, as exposed



28. Lime kiln bank, general north-west view of flues, as exposed



29. Kiln bank façade, north-west end, view south-east



30. Kiln 1, probable location (collapsed), view south-east



31. Kiln 2 draw hole, view south-west



32. Kiln bank façade collapsed between Kilns 1 & 2 and 3-5, view south-east



33. Kiln 3 and external retaining wall, view south-east



34. Kiln 4 and external retaining wall, view south-east



35. Kiln 5 and retaining wall, view south-west



36. Kiln 5, external retaining wall and abutment, view south