DB 12/2/8

Cow Tag 191	Function Code P16.2

Brief Description: [timber element, p/s, condition, fragments]

Fragment – Upper edge fragt aft scarf.

Notable Features: [tool marks, scribed lines, decoration, repairs] POINTS TO LOOK OUT FOR WHEN RECORDING ufos



Wood Science: [rings, ARW, knots, sapwood, conversion]

Radial fag.



Recommended action: [samples, additional photos, moulding, queries and problems]

Cleaned: 30/10/08 KHM	Recorded: 07/09/08 55	Photos:
Checked: [corrections needed] ✓		Initials & Date: WN 8/9/8
Corrections Done [desktop, Faro Arm?]:		Initials & Date: