| Cow Tag 340	Function Code S28,2

Brief Description: [timber element, p/s, condition, fragments]

PART OF PLANK (AFT SCARF)
Wood surface deteriorated.

Notable Features: [tool marks, scribed lines, decoration, repairs] POINTS TO LOOK OUT FOR WHEN RECORDING ufos

iB : Type 1 , forward of timber

Corroded.

Wood Science: [rings, ARW, knots, sapwood, conversion]

Radial c 50H Pith beyond
upper edge. ARW = 220/50.

Recommended action: [samples, additional photos, moulding, queries and problems]

Cleaned: 07/09/06 LB	Recorded: VT 07/09/06	Photos:
Checked: [corrections needed]		Initials & Date: NN 18/10/6
Corrections Done [desktop, Faro Arm?]:		Initials & Date: