| Cow Tag 487	Function Code P7 V10

Brief Description: [timber element, p/s, condition, fragments]

4 SMALL FRAGMENTS   Scarf

Notable Features: [tool marks, scribed lines, decoration, repairs] POINTS TO LOOK OUT FOR WHEN RECORDING ufos

Wood Science: [rings, ARW, knots, sapwood, conversion]

Recommended action: [samples, additional photos, moulding, queries and problems]

Cleaned: BJ 27/04/06	Recorded: 08/11/07 BJ	Photos:
Checked: [corrections needed]		Initials & Date:
Corrections Done [desktop, Faro Arm?]:		Initials & Date: