DB 11/3/8

Cow Tag 390	Function Code P3_2

Brief Description: [timber element, p/s, condition, fragments]

Notable Features: [tool marks, scribed lines, decoration, repairs] POINTS TO LOOK OUT FOR WHEN RECORDING ufos

Borer. - exit holes for one tube on both inboard + outboard.

Wood Science: [rings, ARW, knots, sapwood, conversion]

Straight grained adze/axe/craft scarf
Pith beyond upper edge
9 SH + 5H. ARW = 2.0mm

Recommended action: [samples, additional photos, moulding, queries and problems] Good examples of additional nails between original clinker nails.

Cleaned: 24.02.06 AK/TNJ	Recorded: TNJ 13.03.06	Photos: —
Checked: [corrections needed] ✓		Initials & Date: NN 25/4/6
Corrections Done [desktop, Faro Arm?]:		Initials & Date:


390
390 P3_2 Toby N. Jones 12 March 2006