DB 13/3/8

Cow Tag	Function Code
~~581~~ 581	P2.6

Brief Description: [timber element, p/s, condition, fragments]

Near complete plank with marked bend.

Notable Features: [tool marks, scribed lines, decoration, repairs] POINTS TO LOOK OUT FOR WHEN RECORDING ufos

2 small Fe nails at aft end with head impressions on outboard.
Well defined tool signatures on forward scarf.
Heavily eroded outboard upper land.

Wood Science: [rings, ARW, knots, sapwood, conversion]

c 67H ARW = 170/67. Radial unclear which edge nearest centre
A number of small knots.



Recommended action: [samples, additional photos, moulding, queries and problems]

Mould tool signatures forward scarf.

Cleaned:	Recorded:	Photos: 02/03/06 MMR IN: ADD NAILS - SCARF ~~TOOL~~ TREENAIL ON LAND OUT & OUT: TOOL SIGNATURES + TOOL MARKS
Checked: [corrections needed] Photos of tool signatures fore scarf + small iron nails aft scarf		Initials & Date: OUT: ADD NAILS. NN 9/10/4.
Corrections Done [desktop, Faro Arm?]:		Initials & Date:

3/D


well defined
/ two signatures
581 P2_6 Toby N. Jones 27.09.05
Rivet area
bevel
bevel
bevel
bevel
581
bevel
bevel
bevel
bevel
rear
circular
beveled central
area as marked
1
exit marks
IN
OUT
UP