| Cow Tag	O85	Function Code	S22-6	TI'

Brief Description: [timber element, p/s, condition, fragments]

fragments   Aft Scarf ?

Notable Features: [tool marks, scribed lines, decoration, repairs] POINTS TO LOOK OUT FOR WHEN RECORDING

Upper edge , O.B hnd.

DB 03/12/09

1876

O85

T.1	T.2	T.3	T.4	T.5	T.6	T.7	

Wood Science: [rings, ARW, knots, sapwood, conversion]

Recommended action: [samples, additional photos, moulding, queries and problems]

Cleaned: 21 /09 /08 DS	Recorded: 08/11/07 SJ	Photos:
Checked: [corrections needed]		Initials & Date:
Corrections Done [desktop, Faro Arm?]:		Initials & Date: