



Mortises in rails generally between two studs were a method of fitting studs after the assembly of the main frame members. Not all rails were visible during survey and only those visible at the time have been marked.



Blocked doorway in wall.

INTERNAL ELEVATION IN MIDSTREY TOWARDS WEST



Door inserted for entry to granary lean-to with boards slots either side to restrict entry.

INTERNAL ELEVATION IN MIDSTREY TOWARDS EAST

These elevations taken from Architects drawing of frame survey No. 54/02 and modified to visual survey with added detail. Original scale 1:50 now 90% of that.