




DB 11/2/8

S26-5A

Cow Tag <b>135</b>		Function Code <del>XXXXXXXXXX</del>
Brief Description: [timber element, p/s, condition, fragments] near complete plane - damaged missing aft end piece of upper edge (sap) in attached bag.		
Notable Features: [tool marks, scribed lines, decoration, repairs] POINTS TO LOOK OUT FOR WHEN RECORDING ufos  Smaller than average rover? + rivets?  Add, spike between blinker nail has small head and large shank. Type 1 inboard x 2 Small wooden <del>spike</del> <sup>plus</sup> adjacent to large spike on inboard face of forward scarf.		
Wood Science: [rings, ARW, knots, sapwood, conversion]  true Radial Pith at lower edge 57 H + 8S arw = 195/65		
Recommended action: [samples, additional photos, moulding, queries and problems]		
Cleaned:	Recorded: <del>MMR 10-05-01/5</del>	Photos:
Checked: [corrections needed]		Initials & Date:
Corrections Done [desktop, Faro Arm?]:		Initials & Date:



wood bars  
 20' d  
 20' d



O-Tinglo

1000 0 2

S265A