

DB 12/2/18

Cow Tag **170** Function Code **P8-6 A**

Brief Description: [timber element, p/s, condition, fragments]

Near complete but damaged ~~scar~~ aft scarf


Notable Features: [tool marks, scribed lines, decoration, repairs] POINTS TO LOOK OUT FOR WHEN RECORDING ufos

Type 1 scribed lines in head  
Scribed line defining lead on in head face

Add wood fastener centres layer

Wood Science: [rings, ARW, knots, sapwood, conversion]

C110 H+10 S at forward scarf - Radial.  
ARW =  $\frac{230}{220}$  - Pith beyond lower edge ?



Recommended action: [samples, additional photos, moulding, queries and problems]

Should be coded to P8.6 ✓ TNJ 16.11.06

Take photos of Repair on Outboard

DOND.

Photo showing chatter marks on forward scarf.

Type 1's  
Outboard compression feature with additional marks

Cleaned:

Recorded: ReRecorded 16.11.06

Photos:

24/1/07

HPM/TNJ 04.01.05  
TNJ

Checked: [corrections needed]

Initials & Date:

Corrections Done [desktop, Faro Arm?]:

Initials & Date:

Gone 123/1/7  
MN


DB 15/18

A 98-6


Function Code

170

Cow Tag




^ = measure on timber [ ] = Rhino file.



But v disturbed here.

So gauge at aft scarf

Recorded with 3 + 1 central points.



Recommended action: [samples, additional photos, moulding, queues and problems]

Should be noted to 88 of the report

Handwritten notes and signatures are present in this section.

Recorded	HM/TNT	04.10.07	HM/TNT
Checked: [corrections needed]			
Correctors Done [desktop, Faro Arm?]			
Initials & Date			
Initials & Date			

