


DB 12/2/8

Cow Tag	177	Function Code	P9_8A
Brief Description: [timber element, p/s, condition, fragments]			
Notable Features: [tool marks, scribed lines, decoration, repairs] POINTS TO LOOK OUT FOR WHEN RECORDING ufos Good tool marks on aft scarf Need to add wood features casto layer			
Wood Science: [rings, ARW, knots, sapwood, conversion]			
Recommended action: [samples, additional photos, moulding, queries and problems]			
ReRecorded TNJ 07/11/2006			
Cleaned:	Recorded: TNJ 12.01.05	Photos:	
Checked: [corrections needed]		Initials & Date: 18/04/07 3J VT	
Corrections Done [desktop, Faro Arm?]:		Initials & Date:	