


DB 12/2/8

Cow Tag **206** Function Code **P13-1 C**

Brief Description: [timber element, p/s, condition, fragments]  
Aft Scarf Fragment of P13-1 - modern cut for dendro?

Notable Features: [tool marks, scribed lines, decoration, repairs] POINTS TO LOOK OUT FOR WHEN RECORDING ufos

Wood Science: [rings, ARW, knots, sapwood, conversion]  
Radial, pith beyond upper edge  
C110H+SS. ARW = 197 / 115  
SS  
115 Total Rings Sapwood 5



Recommended action: [samples, additional photos, moulding, queries and problems]  
Check for dendro.

Cleaned:  
TNJ 05.07.06

Recorded:  
TNJ 07.07.06


Photos:

Checked: [corrections needed]  
✓


Initials & Date:  
NN 16/8/6.

Corrections Done [desktop, Faro Arm?]:

Initials & Date:



2006 P13\_1C Toby N. Jones 07 July 2006



modern cut for dendro sample.