

DB 03/12/09

Cow Tag 437 Function Code ~~P10-8~~ P10-7


Brief Description: [timber element, p/s, condition, fragments]

Notable Features: [tool marks, scribed lines, decoration, repairs] POINTS TO LOOK OUT FOR WHEN RECORDING

Fragment needs cow tag added during recording.

T.1	T.2	T.3	T.4	T.5	T.6	T.7	T.8

Wood Science: [rings, ARW, knots, sapwood, conversion]



Recommended action: [samples, additional photos, moulding, queries and problems]

Cleaned: 15/09/07	Recorded: 30/10/07 35	Photos:
----------------------	--------------------------	---------

Checked: [corrections needed]	Initials & Date:
-------------------------------	------------------

Corrections Done [desktop, Faro Arm?]:	Initials & Date:
--	------------------