			Dh	09/	12/0	- Plan	11 45
Cow Tag	450			Function	n Code	- Plan	
Brief Descr	iption: [timbe	er element,	p/s, condition			1 (000	
*							
1 8					Ł	Α	
Notable Features: [tool marks, scribed lines, decoration, repairs] POINTS TO LOOK OUT FOR WHEN RECORDING							
Sample 2860							
Double Treencil- end of scorf							
T.4	Т 2	Т 2	Т.4	T.5	T.6	T.7	ТО
T.1	T.2	T.3	T.4	1.5	1.0	1.7	T.8
Wood Science: [rings, ARW, knots, sapwood, conversion]							
ė.							
	·	⇒/ 	* ×	Ser			ři N
Recommended action: [samples, additional photos, moulding, queries and problems]							
	Faro						
	Photo						
						*	
Cleaned:	*		Recorded:		Photo	os: 10 /	101/08

Initials & Date:

Initials & Date:

Checked: [corrections needed]

Corrections Done [desktop, Faro Arm?]: