

DB 5/3/2008
S15.64

Cow Tag 498


Function Code

Brief Description: [timber element, p/s, condition, fragments]
FRAGMENTS of S15.64

Notable Features: [tool marks, scribed lines, decoration, repairs] POINTS TO LOOK OUT FOR WHEN RECORDING
N.N.F

T.1	T.2	T.3	T.4	T.5	T.6	T.7	

Wood Science: [rings, ARW, knots, sapwood, conversion]



Recommended action: [samples, additional photos, moulding, queries and problems]

Cleaned: 13/09/06 3J

Recorded: 18/01/07 3J

Photos:

Checked: [corrections needed]

Initials & Date: 18/04/07 3J VT

Corrections Done [desktop, Faro Arm?]:

Initials & Date: