




DB 12/3/8

Cow Tag <u>501</u>		Function Code <u>511.5</u>
Brief Description: [timber element, p/s, condition, fragments] <u>Plank in good condition, some sapwood on upper edge</u> <u>Dendro + 2306</u>		
Notable Features: [tool marks, scribed lines, decoration, repairs] POINTS TO LOOK OUT FOR WHEN RECORDING ufos <u>IB: add. nails forward end,</u> <u>OB dimples / impressions around tree rings ca 1m. aft of forward edge.</u> <u>a number of additional nails.</u> <u>Fostener holes in poor condition on fore scarf.</u> <u>IBs Type 2 (2 lines)</u> <u>angle 3mm. pins.</u> <u>re-rec. after slicing for dendro.</u>		
Wood Science: [rings, ARW, knots, sapwood, conversion] <u>Generally straight grain + radial</u> <u>Pit beyond upper edge on front</u> <u>end c/50 H. ARW = 245/150</u>		
Recommended action: [samples, additional photos, moulding, queries and problems]		
Cleaned: <u>MS, VT, LB</u> <u>05/06/06</u>	Recorded: <u>VT</u> <sup>REREC.</sup> <u>19/06/06</u> <sup>LIBB</sup> <u>10/10/07</u>	Photos:
Checked: [corrections needed]	Initials & Date: <u>NN 11/7/6.</u>	
Corrections Done [desktop, Faro Arm?]:	Initials & Date:	

Being recorded by Toby, needs to be checked by Toby.  
16/06/06



501 811.5 Vessels' Details 19 June 2008



↑ compression work?  
Stand for work?

Top 2