

DB 1A/2/8  
P10-115

Cow Tag <b>219</b>		Function Code <b>P10-115</b>
Brief Description: [timber element, p/s, condition, fragments]		
Notable Features: [tool marks, scribed lines, decoration, repairs] POINTS TO LOOK OUT FOR WHEN RECORDING ufos		
<p>~15 wooden spikes/plugs</p> <p>1 staple hole - 2cm deep</p> <p>Numerous additional nails</p> <p>Repair along lower edge</p> <p>2 Tingles - Outboard</p>		
Wood Science: [rings, ARW, knots, sapwood, conversion]		
<p>Radial, some wavy grain, P.H. beyond upper edge. C80H+HS?</p> <p>ARW = 230/80.</p>		
Recommended action: [samples, additional photos, moulding, queries and problems]		
<p>Take photos of repairs</p> <p>Some photos have been taken in the post.</p>		
ReRecorded TNJ 30/11/2006		
Cleaned:	Recorded: TNJ 06.04.05	Photos: VT 24/1/7
Checked: [corrections needed]		Initials & Date: NN 23/1/7
Corrections Done [desktop, Faro Arm?]:		Initials & Date: