




DB 20/2/8

Cow Tag	Function Code
304	519.7A
<p>Brief Description: [timber element, p/s, condition, fragments] DAMAGED PLANK ^{small} LAND MISSING FULL LENGTH, MOST OF AFT SKAFF MISSING Connections V.V.V. had a scratch on - V. HORRIBLE PLANK</p> <p>Notable Features: [tool marks, scribed lines, decoration, repairs] POINTS TO LOOK OUT FOR WHEN RECORDING ufos</p> <p>✓ INJECTED - LOTS OF <u>T.I.</u> lines all over plank, O.B. - wedge on dead T.N from aft end. 3 oversized holes - why?</p>	
<p>Wood Science: [rings, ARW, knots, sapwood, conversion]</p> <p>Wavy (slightly) grain Radial c/10 HD. Pith beyond lower upper edge?</p> 	
<p>Recommended action: [samples, additional photos, moulding, queries and problems]</p>	
<p>Cleaned:</p> <p>17/08/06 SS VT</p>	<p>Recorded:</p> <p>MS 6/9/6</p>
<p>Checked: [corrections needed]</p> <p>✓</p>	<p>Photos:</p> <p>Initials & Date:</p> <p>NN 11/9/6</p>
<p>Corrections Done [desktop, Faro Arm?]:</p>	<p>Initials & Date:</p>



304 S19_7A Matthew Simmonds 5 September 2006



oversized hole.