


DB 11/3/8

Cow Tag **374** Function Code **P8_4**

Brief Description: [timber element, p/s, condition, fragments]

Notable Features: [tool marks, scribed lines, decoration, repairs] POINTS TO LOOK OUT FOR WHEN RECORDING ufos
Repair along upper edge
Needs label, ^{mark} fastener centres layer, sample layers ~~edges~~ need to be transferred to new drawing

Wood Science: [rings, ARW, knots, sapwood, conversion]
52A Radial cut off surf. Pith layer lower edge. First grain. ARW = 22.5/52





Recommended action: [samples, additional photos, moulding, queries and problems]
P Standing central points - Run in flush
TNS 18.10.06

Cleaned: Recorded: Photos:

Checked: [corrections needed] Initials & Date:

Corrections Done [desktop, Faro Arm?]: Initials & Date:



Line 72

374 P8.4