




DB 58/3/2008

Cow Tag 47		Function Code P5-5
Brief Description: [timber element, p/s, condition, fragments] VERY GOOD CONDITION		
Notable Features: [tool marks, scribed lines, decoration, repairs] POINTS TO LOOK OUT FOR WHEN RECORDING ufos WELL VISIBLE IMPRESION MARKS FROM FRAMES - INB. Impression		
Wood Science: [rings, ARW, knots, sapwood, conversion] Radial 85H+5S ARW = 225/90 Centre beyond lower edge		
Recommended action: [samples, additional photos, moulding, queries and problems] DEND ? (2343)		
Cleaned: 21/10/05 HPM, ET, KH SY, MM, AK, CW,	Recorded: HPM 24.10.05	Photos:
Checked: [corrections needed]		Initials & Date: NN 28/10/05
Corrections Done [desktop, Faro Arm?]:		Initials & Date:



417 P5 5 hpm 24/10/05



- axe marks + signature

metal