



DB 13/3/8

Cow Tag 584	Function Code P 2.2.	
Brief Description: [timber element, p/s, condition, fragments]		
Notable Features: [tool marks, scribed lines, decoration, repairs] POINTS TO LOOK OUT FOR WHEN RECORDING ufos Large scribed lines (x2) on outboard upper edge band. Some nice axe marks on scarfs.		
Wood Science: [rings, ARW, knots, sapwood, conversion] c 80 H ARW = 162/80. Radial at forward scarf becoming intermediate at aft scarf Centre beyond lower upper edge? 		
Recommended action: [samples, additional photos, moulding, queries and problems]		
Cleaned: 7	Recorded: 7	Photos: 7
Checked: [corrections needed] NA		Initials & Date: 11/10/5
Corrections Done [desktop, Faro Arm?]:		Initials & Date:



584 P2_2 Toby N. Jones 17.09.05

Fe corrosion product
in filling void holes

Note core split on scarf

1348

1347

1344

1345

1346

1343

1342

1341

1340

1355

1354

1353

1352

1351

1350

1349