


Cow Tag <b>603</b>		Function Code <b>P 9-2</b>
Brief Description: [timber element, p/s, condition, fragments]		
Notable Features: [tool marks, scribed lines, decoration, repairs] POINTS TO LOOK OUT FOR WHEN RECORDING ufos		
<p><del>Need wooden fastener centres layer</del></p>		
Wood Science: [rings, ARW, knots, sapwood, conversion]		
<p>Tangetial. c 80H + \$25. P, H          beyond lower edge. ARW = 205/82          Some wavy grain. large tear in board          forward + grain runs away on aft scarf.</p>		
Recommended action: [samples, additional photos, moulding, queries and problems]		
ReRecorded 01.11.2006		
Cleaned:	Recorded: TNJ 05.01.05	Photos:
Checked: [corrections needed]		Initials & Date: NN 30/1/7
Corrections Done [desktop, Faro Arm?]:		Initials & Date: