


DB

27/02/08

Cow Tag <i>626</i>		Function Code <i>P14.6</i>
Brief Description: [timber element, p/s, condition, fragments] <i>solid plank, somewhat softer face OB</i>		
Notable Features: [tool marks, scribed lines, decoration, repairs] POINTS TO LOOK OUT FOR WHEN RECORDING ufos <i>several inscribed lines, some quite faint both IB &amp; OB, also axemarks and poss auger mark (IB)</i>  <i>Type 1 x 2 IB</i>		
Wood Science: [rings, ARW, knots, sapwood, conversion] <i>CWD A + SS at aft scart. Radial P.A. beyond upper edge. Narrow band of ngs near upper edge here. ARWs 225/105.</i>		
Recommended action: [samples, additional photos, moulding, queries and problems]		
Cleaned: <i>MS/LB</i> <i>07/06/06</i>	Recorded: <i>85</i> <i>12/06/06</i>	Photos:
Checked: [corrections needed]	Initials & Date: <i>27/06/06</i>	
Corrections Done [desktop, Faro Arm?]:	Initials & Date:	


REC'D BY BON

Compensation

Leas

Time 1

Time 7



628 P14, © Ben R. Jennings 12 June 2006

