

DB 07 11/2/09

Cow Tag

672

Function Code

F31.0

Brief Description: [timber element, p/s, condition, fragments]

Fragments . Cannot Place . Not record .

Notable Features: [tool marks, scribed lines, decoration, repairs] POINTS TO LOOK OUT FOR WHEN RECORDING

T.1

T.2

T.3

T.4


T.5

T.6

T.7

T.8

Wood Science: [rings, ARW, knots, sapwood, conversion]



Recommended action: [samples, additional photos, moulding, queries and problems]

Cleaned:

VT
11/12/06

Recorded:

Photos:

Checked: [corrections needed]

Initials & Date:

Corrections Done [desktop, Faro Arm?]:

Initials & Date: