	* 11 - 4	•••	DR	071	ion Code	9	
Cow Tag	673			Functi	ion Code	47.4	Frags
	ription: [timbe					- W	,
Very small	ll tragments	CA	HNOT PL	see. N	RECOR	es.	
Notable Fe WHEN RE		marks, scril	oed lines, de	coration, r	epairs] POII	NTS TO LO	OK OUT FOR
				, *			
	an Y						
	· ·						
Suff		a .					
T.1	T.2	T.3	T.4	T.5	T.6	T.7	T.8
2	ege "				1		
Wood Scie	nce: [rings, A	ARW, knots	, sapwood, d	conversion	]		
						$\bigcirc))))))$	
							4
							e la
Recommer	nded action:	[samples, a	dditional pho	otos, moul	ding, querie	s and proble	ems]
***							8
	*						
1							
Cleaned:	VI		Recorded:		Photo	00:	

Photos:		
2	v	
Initials & Date:		
Initials & Date:		
	Initials & Date:	