Cow Tag	089	5	<u></u>	Function	Code	517.	DB	6/2/
Brief Descr			p/s, condition	fragments		<u> </u>	<u> </u>	
			id , upper	-				
Notable Fe WHEN RE	atures: [tool	marks, scri	bed lines, dec	oration, repa	irs] PO	INTS TO	LOOK	OUT FOR
B: wsca	bed fines		•					
	marks ou	level.						
,	•							
			*					
-								
T.1	T.2	T.3	T.4	T.5	T.6	T.7		
Wood Soio	nce: Irings A	DIM knoto	 , sapwood, co	nversion1				
<u></u>		·	alaliti a a a l a la a t					
Recommer	ided action: [	sampies, a	dditional phot	os, moulaing	ı, queri	es and p	roblemsj	İ
	,							
Cleaned:	/ /	RTF	Recorded: V1	<u> </u>	Pho	tos:		
21	104/06	ارک	12/12/	00				
Checked: [	corrections n	eeded]			Initia	als & Dat	te:	RT
					01	124	107	33
Corrections	Done [desk	top, Faro A	.rm?]:		Initia	als & Dat	te:	VI
	-	-	-		1			