DB 26/2/8

Cow Tag	Function Code
328	S28.5

Brief Description: [timber element, p/s, condition, fragments]

complete, shorter plank, edge = 327

Notable Features: [tool marks, scribed lines, decoration, repairs] POINTS TO LOOK OUT FOR WHEN RECORDING ufos

T6 JB inscribed line ~~2ghtA~~ New type A -> see step. 327

T1 OB : face of where tingle was added

add. treenail / plug
double treenail
add nail on s éb scarf
Nail through treenail

good tool marks with good tool signatures - good cand. date for casting - all add. nails for tingle are longer than ord. nails and on the fore + AFt side of each nail hole the wood has been pushed up - not on other edges nor on any other nail

Wood Science: [rings, ARW, knots, sapwood, conversion]

Radial but incomplete to ms cent



Recommended action: [samples, additional photos, moulding, queries and problems]

Add missing nail ?

Moulding?

Cleaned:	Recorded:	Photos:
06/09 / LB	MS 7/9/16	
Checked: [corrections needed] ✓		Initials & Date: NN 11/9/16
Corrections Done [desktop, Faro Arm?]:		Initials & Date:



missing nail