| Cow Tag	362	Function Code	S30.3B	**OB 11/3/8**

Brief Description: [timber element, p/s, condition, fragments]

Plank in good cond. although somewhat damaged. edges

Notable Features: [tool marks, scribed lines, decoration, repairs] POINTS TO LOOK OUT FOR WHEN RECORDING

OB: Type 4, double X

IB: poss type 1 next to scarf

| T.1	T.2	T.3	T.4	T.5	T.6	T.7	
✓					✓		

Wood Science: [rings, ARW, knots, sapwood, conversion]

Radial. 105 H. Pith beyond lower edge? ARW = 200/105.

Recommended action: [samples, additional photos, moulding, queries and problems]

| Cleaned: 19/09/06 VT, EC	Recorded: MS 2/9/6	Photos:
Checked: [corrections needed] ✓		**Initials & Date:** NN 17/10/6
Corrections Done [desktop, Faro Arm?]:		**Initials & Date:**

826 S30_3B Matt Simmonds 21 September 2006

Production wrong
Changed NN
25/10/6