Cow Tag	422	Function Code	T/NG/E L ≤28.51

Brief Description: [timber element, p/s, condition, fragments]

Notable Features: [tool marks, scribed lines, decoration, repairs] POINTS TO LOOK OUT FOR WHEN RECORDING

I.B. N.N.F axe marks

O.B. - Lots of lines along length of plank
double 'o' c. middle of plank -
clamp work?

NB No rebates = later repair?

T.1 ✓	T.2	T.3	T.4	T.5	T.6	T.7	

Wood Science: [rings, ARW, knots, sapwood, conversion]

c 70H ?? Radial

Recommended action: [samples, additional photos, moulding, queries and problems]

DGND.

Cleaned: 13/09/06 BB	Recorded: VT 13/09/06	Photos:
Checked: [corrections needed]		**Initials & Date:** NN 9/10/1.
Corrections Done [desktop, Faro Arm?]:		**Initials & Date:**