DB 12/3/8

Cow Tag: S21	Function Code: S 6.5

Brief Description: [timber element, p/s, condition, fragments]
GOOD CONDITION

Notable Features: [tool marks, scribed lines, decoration, repairs] POINTS TO LOOK OUT FOR WHEN RECORDING ufos

INBOARD:- STEP IN LAND, c. 1 m FROM AFT END
" " " " 0.6 m " FORE END
clamp impression horn upper edge

OUTBOARD:- POSSIBLE STAIR ON AFT EDGE OF 4th
NAIL HEAD IMPRESSION ON UPPER EDGE OF
PLANK FROM AFT END OF PLANK

Wood Science: [rings, ARW, knots, sapwood, conversion]

c110 radial pith beyond upper edge?
ARW = 235/110.



Recommended action: [samples, additional photos, moulding, queries and problems]
photo: inboard face (middle section) ꝏ-shaped impression

Cleaned: JJ NJ 19/05/06	Recorded: Deni 24-6-2006	Photos:
Checked: [corrections needed]		Initials & Date:
Corrections Done [desktop, Faro Arm?]:		Initials & Date: