DB 19/2/8

Cow Tag	Function Code
248	TINGLE (OB)

Brief Description: [timber element, p/s, condition, fragments]

TINGLE - S 24.4 - S24.5

Notable Features: [tool marks, scribed lines, decoration, repairs] POINTS TO LOOK OUT FOR WHEN RECORDING ufos

INBOARD:- ~~Cutting~~ LUTING - upto 3 - 4 mm for end
" - " 5 mm aft end (upto 10 mm in ace niche)

outboard:- possible toolmarks & for end

AFT EDGE POSSIBLY SAWN?
Series of Type 3 drawnnds along crack outboard from foremast, upper rail.

Wood Science: [rings, ARW, knots, sapwood, conversion]

Pith beyond upper edge.
Marked growth band.
c 60 A ARW = 165/60.
Radial



Recommended action: [samples, additional photos, moulding, queries and problems]

Need to check possible saw cut on end (aft).
Photo type 3 lines at crack forward OB.

Cleaned:	Recorded:	Photos:
27/07/06 SS	AK 28/7/6.	MS 15/9/6
Checked: [corrections needed] ✓		Initials & Date: NN 28/7/6.
Corrections Done [desktop, Faro Arm?]:		Initials & Date: