| Cow Tag 301	Function Code filler between F10.2 and coco 2035

Brief Description: [timber element, p/s, condition, fragments]

Filler.

Notable Features: [tool marks, scribed lines, decoration, repairs] POINTS TO LOOK OUT FOR WHEN RECORDING

Rec as starboard.
Nail on edge JB → at an angle so that it is not visible on the OB.

T.1	T.2	T.3	T.4	T.5	T.6	T.7	T.8

Wood Science: [rings, ARW, knots, sapwood, conversion]

$$ARW = \frac{125}{33}$$

Tangential Sawn

Recommended action: [samples, additional photos, moulding, queries and problems]

| Cleaned:	Recorded: ZBR 07/11/04	Photos:
Checked: [corrections needed]		Initials & Date: 27/1/9 BJ se
Corrections Done [desktop, Faro Arm?]:		Initials & Date:

8co
190T

DB 29/01/09

Cow Tag	301	Function Code Not AVAIL. ceiling Plank?

Brief Description: [timber element, p/s, condition, fragments]

fragment

Notable Features: [tool marks, scribed lines, decoration, repairs] POINTS TO LOOK OUT FOR WHEN RECORDING

Lots of tool marks, both Sides

T.1	T.2	T.3	T.4	T.5	T.6	T.7	T.8

Wood Science: [rings, ARW, knots, sapwood, conversion]

Recommended action: [samples, additional photos, moulding, queries and problems]

Cleaned: 18/09/08 BJ	Recorded:	Photos:
Checked: [corrections needed]		**Initials & Date:**
Corrections Done [desktop, Faro Arm?]:		**Initials & Date:**