Cow Tag 564	Function Code P2.4

Brief Description: [timber element, p/s, condition, fragments]
GOOD CONDITION - LAND WITH #75 ± ∠ 45°; ~~TWO INTENTICH~~ QUATE
~~&~~ THICK

Notable Features: [tool marks, scribed lines, decoration, repairs] POINTS TO LOOK OUT FOR WHEN RECORDING ufos
ON THE INBOARD FACE TWO INTENTIONAL MARKS, ON THE
LAND ~~WE~~ VERY WELL VISIBLE TOOL MARKS. ~~SOME~~
~~PART OF THOUSE MAI TO MARKS HALE~~

Wood Science: [rings, ARW, knots, sapwood, conversion]

This is
~~ON~~'— NN.

Radial with bevel on inboard last
cutting across grain — see drawing
Age tree? If so path beyond upper
ledge. c.110↓ ARW = 195/110.

Recommended action: [samples, additional photos, moulding, queries and problems]

BJ
Re Rec'd 30/08/07

Cleaned: 5/09/05 MM	Recorded: 12/09/05 MM	Photos: B/D 5/09/05 INSCRIBE MARKS, ⊥ OF LAND (MM)
Checked: [corrections needed]		Initials & Date: NN 4/11/5
Corrections Done [desktop, Faro Arm?]:		Initials & Date:

TOOL SIGNATURES

620

564