DB 13/3/8

Cow Tag 583	Function Code 52.8

Brief Description: [timber element, p/s, condition, fragments]

Near complete plank

Notable Features: [tool marks, scribed lines, decoration, repairs] POINTS TO LOOK OUT FOR WHEN RECORDING ufos

Heavily worked inboard face.

Wood Science: [rings, ARW, knots, sapwood, conversion]

Radial, Centre beyond lower edge

c 80H ARW = 18 1/60



Recommended action: [samples, additional photos, moulding, queries and problems]

Cleaned:	Recorded: TNJ 02.10.05	Photos: 09/03/06 MMR IN: TOOL SIGNATURES INS. LINES OUT: TREENAIL WITH DIMPLE B/D
Checked: [corrections needed] NN.		Initials & Date: 11/10/5
Corrections Done [desktop, Faro Arm?]:		Initials & Date:


UP
OUT
IN
583
photo
photo