OB 13/3/8

Cow Tag 595	Function Code S4-7

Brief Description: [timber element, p/s, condition, fragments]
GOOD ~~CONDITION~~ CONDITION

Notable Features: [tool marks, scribed lines, decoration, repairs] POINTS TO LOOK OUT FOR WHEN RECORDING ufos

2 PLUGGED HOLES AFT OF FORW. END, LOWER + UPPER EDGE

1 — ¼" — HOLE AFT OF OUTBD. SCARF, UPPER EDGE

4 PLUGGED HOLES CA. MIDDLE OF PLANK, 2 AT LOWER, 2 AT UPPER EDGE

1 PLUGGED HOLE ~~A~~ FORW. OF AFT END, LOWER EDGE

———— " ————, MIDDLE OF PLANK

2 ADD. NAILS FORW. OF AFT END, RIGHT BY THE EDGE

SOME DIMPELS ON TREENAILS Type 3 scribed < inboard forward edge.

Wood Science: [rings, ARW, knots, sapwood, conversion]
Offradial 85 H. + SS. Pith beyond lower edge ARW: 200/90.



Recommended action: [samples, additional photos, moulding, queries and problems]
DEVIATION: x-axis: 0.176 mm
y-axis: 0.691 mm
} LAST 50 cm OF AFT END OF OUTBD. FACE

Cleaned: 28/03/06 AK, MMR	Recorded: 10.04.06 AK.	Photos:
Checked: [corrections needed] Average length of forward stack → scribed line (Type 3)		Initials & Date: NN 25/4/6
Corrections Done [desktop, Faro Arm?]:		Initials & Date:


F45
change to scribed line
(Type 3)
F 50
595
595 S4_7 Angela Karsten 4 April 2006