DB 7/2/18

| Cow Tag 095. | Function Code S9.1 |
|---|---|

Brief Description: [timber element, p/s, condition, fragments]

Damaged at forward end — poss match with piece from bow excavation?

Notable Features: [tool marks, scribed lines, decoration, repairs] POINTS TO LOOK OUT FOR WHEN RECORDING ufos

Wooden Spikes
Add nails
Good Axe marks.

Wood Science: [rings, ARW, knots, sapwood, conversion]

Hard to see but near radial path at upper edge
105 H ARW = 196/105

Sapwood.



Recommended action: [samples, additional photos, moulding, queries and problems]

Photo on head forward nail/head + wooden nail relationship? ~~on upper edge~~

| Cleaned: ✓ | Recorded: Re Recorded TNJ 25/1/7 ~~AMR 11.5.5~~ | Photos: * DETAIL SHOT - CAULKING MAT. AROUN NAIL HOLE. 25/02/05 mm |
|---|---|---|
| Checked: [corrections needed] Photo as above | | Initials & Date: ~~NN 17/5/5~~ NN 30/1/7 |
| Corrections Done [desktop, Faro Arm?]: | | Initials & Date: |

S9.1

CONTAG 095




change to add nail

need to add head + photo.



change to add nail