


W

DB 03/12/09

Cow Tag 143		Function Code S 20.2
Brief Description: [timber element, p/s, condition, fragments] # Number of Fragments of S 20.2		
Notable Features: [tool marks, scribed lines, decoration, repairs] POINTS TO LOOK OUT FOR WHEN RECORDING. ufos Central - upper of for scarf.		
Type 3 Lines (x2) 1.13 one on a one of.		
Wood Science: [rings, ARW, knots, sapwood, conversion]		
		
Recommended action: [samples, additional photos, moulding, queries and problems]		
Cleaned: 04/05/06 BS	Recorded: 14/4/07 BJ	Photos:
Checked: [corrections needed]		Initials & Date:
Corrections Done [desktop, Faro Arm?]:		Initials & Date: